



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SJJ6262A

Lim Seo Hong

Blk 75 Pasir Panjang Hill  
#05-01  
Singapore 118885

## Vehicle &amp; Document Information

WIP No 43648  
Reg No/Reg Date SJJ6262A / 25/06/2018  
Date In/Mileage SJJ6262A  
Chassis No WDD2130422A402422  
Engine No 27492031352453  
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE  
Colour/Trim 029 997 Kallaitte Gr/ 042 214 LeatherHaze

Account No	Terms	Date/Time Printed	CSE	Operator			
WCV35835	CRDVCH	09/07/2020/ 16:06	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

## 2 REQUEST

Customer Request

M-BPNSUN

POLICY NO/ACC DATE : MT/00656669 // 06/07/2020  
DRIVE IN/EXCESS : 09/07/2020 // TP VEH NO SHA9526R FIRST CAP. INS.  
DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

S BPNSUB

INSTALL SOLAR FILM ON REAR W/SCREEN

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLAGE WITH NEW  
BODY PANELS WITH REFINISH

A BPIRES

RESpray RIGHT REAR FENDER, RIGHT REAR DOOR, REAR BUMPER AND REAR  
END PANEL

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO  
STANDARD SETTINGS. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET

A BPILAB

TRANSFER MECHANICAL &amp; ELECTRICAL COMPONENTS OVER TO NEW DOOR. NETT

A BPILAB

RENEW REAR W/SCREEN photo?

A BPILAB

REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS, TRIMS BOARDS AND  
SEATS CUSHIONS FOR NEC. REPAIRS

A BPILAB

REMOVE & REFIT FUEL TANK FILLING HOSE, DRAIN AND REFILL FUEL  
FOR NEC. REPAIRS. NETT

A BPILAB

REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS

300.00

4800 5760.00

2100 2400.00

0.10 380.00

120.00

480.00 X

0.07 560.00

1200.00 960

420.00

1920 2400.00

Confirmed &amp; accepted by

Yik Chan Hoe

Cycle &amp; Carriage Industries Pte Ltd

Body Care &amp; Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SJJ6262A

Lim Seo Hong

Blk 75 Pasir Panjang Hill  
#05-01  
Singapore 118885

## Vehicle & Document Information

WIP No 43648  
Reg No/Reg Date SJJ6262A / 25/06/2018  
Date In/Mileage SJJ6262A  
Chassis No WDD2130422A402422  
Engine No 27492031352453  
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE  
Colour/Trim 029 997 Kallaitte Gr/ 042 214 LeatherHaze

Account No	Terms	Date/Time Printed	CSE	Operator			
WCV35835	CRDVCH	09/07/2020/ 16:06	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

THIS IS NOT AN OFFICIAL TAX INVOICE								540.00
A BPILAB								60.00
INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT								
S BPNSUB								
TRANSER TYRE OVER TO NEW RIM								
M	RIGHT REAR DISK WHEEL	sun	1.00	759.71	00.00			759.71
M	RIGHT REAR SHOCK ABSORBER	?	1.00	574.61	00.00			574.61
M	RIGHT REAR WHEEL CARRIER	?	1.00	1651.86	00.00			1651.86
M	RIGHT REAR WHEEL FLANGE	?	1.00	470.99	00.00			470.99
M	RIGHT REAR SPRING LINK ARM	?	1.00	249.19	00.00			249.19
M	REAR W/SCREEN	new photo	1.00	1477.30	00.00			1477.30
M	ONE-COMPONENT ADHESIVE	new	2.00	156.83	00.00			313.66
M	RIGHT REAR FENDER	blue	1.00	2296.77	00.00			2296.77
M	RIGHT REAR FENDER VENTILATION FLAP	?	1.00	26.26	00.00			26.26
M	FUEL TANK FILLER RECESS	?	1.00	216.82	00.00			216.82
M	REAR BUMPER	de	1.00	2021.87	00.00			2021.87
M	RIGHT REAR BUMPER SIDE STABILITY	?	1.00	83.62	00.00			83.62
M	RIGHT REAR DOOR	repair	1.00	2337.96	00.00			2337.96
M	RIGHT REAR DOOR WEATHERSTRIP	?	1.00	305.97	00.00			305.97
M	RIGHT REAR DOOR INSULATION	?	1.00	37.13	00.00			37.13
M	RIGHT REAR DOOR WINDOW GUIDE RAIL	X	1.00	184.65	00.00			184.65
M	TS TWO-COMPONENT ADHESIVE	new	1.00	776.81	00.00			776.81

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 28,405.18  
7% GST on 28405.18 1988.36  
Total Payable 30,393.54

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.