

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Due 29/7/20
3/8/2020
Survey & repair
Charge to
21/7/2020
08 JUL 2020



Estimate No. : b1 55472 Page No. : 1 of 5
Date Estimated : 08/07/2020
Prepared By : Chua Kee Sin

ESTIMATE REPAIR FOR -

Leong Swan Swan
17 Barker Road

Singapore 309892

- ACCOUNT - 40000

Cash Sales - Service
Singapore

VEH. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
LV783R	WBA2H320X0VB97357	21/12/2017	218iA/2	0

DESCRIPTION

VALUE

Replace rear bumper include remove attachment etc

850 1,038.00

Spray painting rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

120 481.00

Sundries.

40 150.00

Total Labour 1: 2,934.00

DESCRIPTION

QTY

PRIC

VALUE

RUBBER MOUNTING ? xsvl	2	17.70	35.40
TAILPIPE TIP BLACK CHROME sca	1	123.40	123.40
REAR SILENCER ? xsvl	1	918.20	918.20
CLAMPING BUSH D=58MM ? xsvl	2	59.45	118.90
SET MOUNTS PDC SENSOR REAR ? xsvl	1	58.90	58.90
REAR BUMPER CARRIER ? xsvl	1	418.55	418.55
REAR BUMPER CENTRE GUIDE ? xsvl	1	61.35	61.35
REAR BUMPER TRIM STRIP (LINE SPORT) ca	1	91.15	91.15
REAR BUMPER PANEL PRIMED (LINES) de	1	1,024.65	1,024.65
RR FLAP TOWING EYE PRIMED sca xsvl	1	39.15	39.15
LEFT PROTECT ? xsvl	1	12.85	12.85
RIGHT PROTEC ? xsvl	1	12.85	12.85
LH REFLECTOR ? xsvl	1	37.75	37.75
RH REFLECTOR ? xsvl	1	37.75	37.75
PDC sensor ? xsvl	4	370.00	1,480.00
DECOUPLING RING PDC TORQUE CONVERTE ? xsvl	4	5.10	20.40

Total Parts : 4,491.25

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 55472
Date Estimated : 08/07/2020
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV783R	WBA2H320X0VB97357	21/12/2017	218iA/2	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 21/07/2020 @ 1355 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90060068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Pray before paint

7,478.30



Labour 1	:	2,934.00
Parts	:	4,491.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	519.77
Grand Total	:	<u>7,945.02</u>

* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



Supplementary

Estimate No. : b1 55472
Date Estimated : 08/07/2020
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -

Leong Swan Swan
17 Barker Road

Singapore 309892

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV783R	WBA2H320X0VB97357	21/12/2017	218iA/2	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# (DG/SL) ADHESIVE SET K6 NEC 	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	53.05
Total Labour & Parts :	53.05