

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMH 6253B
TP/FL

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES2090517/YISHUN

Date: 15 Jul 2020

Policy No: 5107317461-01

Veh Reg No: SMH6253B

Make/Model: HYUNDAI HYUNDAI

AD AVANTE 1.6 GLS
(A) S

Chassis No: KMHD841CMKU845689

Engine No: G4FGJU074730

Reg. Date: 29/01/2019

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 24/06/2020

TP Veh Reg No: SHB2194E

Not Whisker

Putty Bypain

2 days

Estimate Repair Cost to Vehicle No :SMH6253B

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER TOP	459.40	1 PC	459.40	✓
2 REAR BUMPER LOWER	353.50	1 PC	353.50	✓
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
			833.90	
		Less 20%	166.78	667.12
Special Net				
4 REVERSE SENSOR	200.00	1 SET	200.00	✗
			200.00	200.00
Labour				
5 REMOVE & REFIX REAR BUMPER ASSY,LAMPS & REVERSE SENSOR,TO KNOCK & REPAIR REAR BUMPER REINFORCEMENT & REALIGN THE SAME	350.00	1 LA	350.00	250
6 PUTTY & RESPRAY ON REAR BUMPER	300.00	1 LA	300.00	220
			650.00	650.00
Total			S\$ 1,517.12	
Add GST @ 7%			106.20	
Total Amount Payable			S\$ 1,623.32	

Supp

1pc rear bumper w/ reflector \$201.70
20%
40.34

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants (PTE) LTD
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: