



Blok 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
Tel: 6484 1221 Fax: 6484 7829
385 Sio Ailing Drive

385 Sin Ming Drive (Inside Vicom) Singapore 575718.
Tel : 6753 2112 Fax : 6484 7829

Co. Reg No.: 200005485N GST Reg No.: 20-0005485-N

Vehicle No. : **SLZ 4871 Y**
Make & Model : **HONDA SHUTTLE**

Submit By : Carmen Lim

Year of Manufacture : 43221

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569586.

Tel : 6484 1221

Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112

Fax : 6451 0394

Co. Reg No. : 200005485N

GST Reg No. : 20-0005485-N

Spare Parts

Vehicle No. :

SLZ 4871 Y

Make & Model :

HONDA SHUTTLE

Chassis No. :

GP71205651

Submit By :

SERENCE

Year Manufacture :

May-18

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>mg cm</i>	1	\$1,080.00	✓	✓
2	Front bumper clip <i>ma</i>	10	\$40.00	✓	✓
3	Front bumper side retainer LH <i>su</i>	1	\$20.40		X
4	Front bumper side retainer RH <i>su</i>	1	\$20.40		X
5	Front bumper bracket LH <i>R</i>	1	\$38.00		X
6	Front bumper bracket RH <i>R</i>	1	\$38.00		X
7	Headlamp RH <i>mg cm</i>	1	\$2,250.00	✓	2 ✓
(8)	RH wing mirror (back) <i>cm</i>	1	\$587.50	✓	✓
9	RH wing mirror (glass)	1			
10	RH wing mirror (cover) <i>mi</i>	1	\$57.30	✓	✓
(11)	RH front door <i>R</i>	1	\$787.20	✓	✓
12	RH wing mirror (cover) <i>Requon</i>	1	\$57.30		X
13	RH front door <i>u</i>	1	\$787.20		X
14	RH front door hinge top <i>R</i>	1	\$58.60		X
15	RH front door hinge bottom <i>R</i>	1	\$58.60		X
16	RH front door stand pillar sticker <i>ma</i>	1	\$35.80	✓	✓
(17)	RH quarter glass <i>Cur</i>	1	\$290.70	✓	✓
(18)	RHF door glass outer moulding <i>Red</i>	1	\$65.00	✓	✓
19	RHF rim <i>Red</i>	1	\$389.00	✓	✓
20	RHF tyre <i>su</i>	1	\$350.00	S.N	X
21		1			
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

(518) 50 ✓



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel: 6484 1221

Fax: 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel: 6753 2112

Fax: 6451 0394

Co. Reg No.: 200005485N

GST Reg No.: 20-0005485-N

Repair Estimates

SLZ 4871 Y

Finished.

Not Authorised
Henry B4 paint

Parts	(a) Cost / List Price Items	\$ 5580.50	6,661.00
	Plus/Less 20%	\$ 1116.50	1,332.20
	Total of Cost / List	\$ 4466	5,328.80
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$ 0	350.00
Total Parts Cost		\$	5,678.80
Labour		\$ 1330	2,310.00
Total		\$ 5796	7,988.80

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

ELK

Survey conducted on

16/7/20

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Le

Date:

16/7/20