Senneth	2000 7346/K+ ASSIGNMENT
From:	
Estimated Cost:	Veh No: 517 48714 Yr Regn: 05, 1
OD (F) WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
To Inspect Vehicle No:	Type: M.Car/M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailer or A Shuttle c.c / 8  Make: / funds Shuttle c.c / 8
	Make: funds Shuttle c.c 18
at Workshop m/s Estern	Colour M. P. White AC: Insured / Std / NI / NA
Insured:	Sp.Reading / PROS T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
	CNO: GP7 . 12056
Ctalms No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked J Burnt or
Make of Veh:	Modi: NII / STRIM' STD A/RIM or
	Tyre Size: F: 205/50R16
(Policy Condition)	' R:
Remark: The veh had commenced its N/S C repair at the time of inspection.	DS U BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYOTYOKO or /alken
Bal. or Market Value:	<u>Eronl</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal mm R/Bal mm
GIA / PR Seen: Consistent?: Yes or No  Est. Repairs: 05 days Res.: Yes or No	L/Bal. 7 mm L/Bal. 6 mm
10.	D.O.A. 13/7/20 D.O.I. 16/7/202
Lum Sum: //3 / % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OU	
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
PART BY PART \$57	796.00( <del>Red:1378.48; 17%)</del>
toTimo, File Pass 10? Prell. Report	Days Of Repair: 5
1 1 1	Resurvey No. of Tri
	Transaction
Add Fee:	: Site Insp (\$
	Interview (\$
	Tech love (\$
	The same and the s
port Format :	Weekend (\$



Labour

Total

# ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel: 6484 1221 Fax: 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718. Tel: 6753 2112 Fax: 6451 0394

Co. Reg No.: 200005485N GST Reg No.: 20-0005485-N

Not Nothanke Mexing BG pains

_	- Fstimates
Renail	· Estimates

SLZ 4871 Y

D4-	(a) Cost / List Price Items	\$	6,661.00
Parts	Plus/Less20%	\$	1,332.20
	Total of Cost / List	\$	5,328.80
	(b) Nett Price Items	_	
	Less	1	
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	350.00
Total	Parts Cost	\$	5,678.80
, Juli			

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor	Kenneth	
Company		
Survey conducted on	:18/1/26at	
Remarks By Surveyor		
(a) The repair of this vehicle is a	horized / is not authorized until further notice.	
(b) Recommended Days of Rep		
(c) Resurvey	: Required / Not Required	
(d) Excess	:\$	
(e) Signature of surveyor	Le Date: 16/7/20	

2,310.00

7,988.80



### **ESTEEM PERFORMANCE PTE LTD**

Bik 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel: 6484 1221 Fax: 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel: 6753 2112 Fax: 6451 0394

Co. Reg No.: 200005485N GST Reg No.: 20-0005485-N

**Spare Parts** 

Vehicle No. : Make & Model : SLZ 4871 Y

Submit By :
Year Manufacture :
Engine No. :

SERENCE May-18

Chassis No :

HONDA SHUTTLE GP71205651

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper	myon	1	\$1,080.00		-
2	Front bumper clip	M	10	\$40.00		<u></u>
3	Front bumper side retainer LH	Sh	1	\$20.40		X
4	Front bumper side retainer RH	Sn	1	\$20.40	- P. S. T.	٨
5	Front bumper bracket LH	R	1	\$38.00	.<2	X
6	Front bumper bracket RH	1	1	\$38.00	100	X
7	Headlamp RH		1	\$ <mark>2,250.00</mark>		7
8	RH wing mirror (back)	cm	1	\$587.50		<u></u>
9	RH wing mirror (glass)		. 1		. 4	
10	RH wing mirror (cover)	mil	1	\$57.30	Janes	
11	RH front door	A	1	\$787.20		
12	RH wing mirror (cover)	Rejuden	1	\$57.30	-	X
13	RH front door	4	1	\$787.20		X
14	RH front door hinge top	N	1	\$58.60		X
15	RH front door hinge bottom	N	1	\$58.60		X
16	RH front door stand pillar sticker	Ma	1	\$35.80		
17	RH quarter glass	Cor	1	\$290.70		
18	RHF door glass outer moulding	Per	1	\$65.00		
19	RHF rim	Pat	1	\$389.00	7 1-1	
20	RHF tyre	5	. 1	\$350.00	S.N	X
21	No.	100	1			
22						
23	3					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.



## **ESTEEM PERFORMANCE PTE LTD**

Bik 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
Tel: 6484 1221 Fax: 6484 7829
385 Sin Ming Drive (Inside Vicom) Singapore 575718,
Tel: 6753 2112 Fax: 6451 0394
Co. Reg No.: 200005485N GST Reg No.: 20-0005485 N

### Labour

Vehicle No.	:	SLZ 4871 Y	Submit By	:	Carmen Lim	-0.0
Make & Model		HONDA SHITTI E	Year of Manufacture :		43221	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR,		
	RH SIDE MIRROR)	\$1,000.00	5001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR,		-//
	RH SIDE MIRROR)	\$1,000.00	6601
3	To check wiring, focus headlamp	\$50.00	201
4	To tuff coat.	\$50.00	301
5	To do wheel alignment.	\$60.00	~
6	To remove & refit Door trim, door glass, window regulator,		· **
	door lock to assist work load.	\$150.00	601
		7 Y	To.
		i was	
			1/8/1
	1		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary. MVA220059437 / VAC - Sin Ming ENTRY DATE & TIME: 14/07/2020 15:36 SUBMITTED BY: James Ng Wing Kin

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
   This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- T. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	14/07/2020 15:36
Date Of Accident	13/07/2020 17:30
Exact Location Of Accident	140 PETIR ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLZ4871Y
Insured/Policyholder	
Name Of Registered Owner	TASTY RIGHT TRADING
Co Reg No	5XXXX376A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90223202
Alternative Phone No	OFFICE-90223202
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO CONTRACTOR OF THE PROPERTY
Policy Number	5100455360-02 (CLASSIC)
Cover Note Number	
Oriver Control of the	
lame of Driver	LOW HONG KHEE
IRIC No	SXXXX229E
Date Of Birth	06/05/1953
Occupation	OUTDOOR
Pate Of Driving Pass	02/12/1972
Priving Experience	47 YEARS AND 7 MONTHS
Sender	MALE
fobile Number	(LOCAL) +65-90223202
ax Number	,
contact Number	
Mail Address	NOEMAIL

Page 1 of 20

Address BLK 167B SIMEI LANE #03-14 Postcode 522167 Was driver an employee of the Insured's Company YES If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident COLLISION - CHANGE/CROSS LANE Type Of Accident CLEAR Weather Conditions DRY Road Surface Other Information Was any foreign vehicle involved in this accident? Number of vehicles (including own vehicle) involved in the accident Was any body injured in the Accident? Was any injured conveyed to hospital by NO Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. Number of Passengers (Including Driver) Details of Police Action Was the accident reported to the police? NO If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes,against whom? Circumstances of Accident REFER STATEMENT (ATTENDED BY: JAMES NG) Attachment(s) Are accident photos available for attachment? YES Was there any video captured by Car Camera? CANNOT BE UPLOADED Remarks/ Reasons: Was there any audio recorded? DETAILS OF OTHER VEHICLE PROPERTY 1 SLD2982P Vehicle Registration Number Vehicle Make/Model/Colour Details Of Properties PRIVATE CAR Vehicle Category Name of Driver NRIC/Passport Number Contact Number Address Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

Page 2 of 20

Sketch Plan #2 Pg. 1 DECLARATION

TASTW PRICE TO THE ADMINISTRATE THE IN EVEry respect.

200 Jahan Sultan

#03-17 Textillo-Contro
Grandshof Penn 199018
Date & Time:
(If driver is not the policyhold)

(If driver is not the policyholder)

GIAPMC SketchPlanForm V 4 JUL 2020

Page 4 of 20

Reporting Centre Personnel's Signature Name:
NEWWING KIN JAMES
admin.vac@vicom.com.sg