

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA FREED HYBRID
 Engine/Chassis No.: GB71084742
 Date of accident:
 Damaged area: Rear

Date: 20/07/2020
 Claim Type: TP
 VRN: SML6474J



S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate	1	\$ 2,150.00	\$ 2,150.00
2	Tailgate lock	1	\$ 285.00	\$ 285.00
3	Tailgate lock sensor	1	\$ 320.00	\$ 320.00
4	Tailgate weatherstrip	1	\$ 221.00	\$ 221.00
5	Tailgate 'HONDA' logo	1	\$ 99.70	\$ 99.70
6	Tailgate 'FREED' emblem	1	\$ 79.80	\$ 79.80
7	Tailgate 'HYBRID' emblem	1	\$ 65.00	\$ 65.00
8	Tailgate chrome moulding	1	\$ 385.00	\$ 385.00
9	Tailgate lamp	2	\$ 590.00	\$ 1,180.00
10	Rear windscreen moulding	1	\$ 194.00	\$ 194.00
11	Rear bumper	1	\$ 1,299.30	\$ 1,299.30
12	Rear bumper side retainer	2	\$ 76.00	\$ 152.00
13	Rear bumper bracket	2	\$ 68.00	\$ 136.00
14	Rear bumper reinforcement	1	\$ 691.70	\$ 691.70
15	Rear bumper sponge	1	\$ 161.50	\$ 161.50
16	Rear bumper reflector	2	\$ 199.20	\$ 398.40
17	Rear bumper reflector inner bracket	2	\$ 56.00	\$ 112.00
18	Rear bumper tow cover	1	\$ 69.50	\$ 69.50
19	Taillamp	2	\$ 689.00	\$ 1,378.00
20	Taillamp panel	2	\$ 165.00	\$ 330.00
21	Smart buzzer sensor	1	\$ 269.00	\$ 269.00
22	Rear antenna sensor	1	\$ 281.70	\$ 281.70
23	End panel	1	\$ 785.00	\$ 785.00
24	End panel top garnish	1	\$ 284.00	\$ 284.00
25	Tailgate hinge	2	\$ 135.00	\$ 270.00
26	Tailgate absorber	2	\$ 177.00	\$ 354.00
27	Tailgate stopper	2	\$ 16.00	\$ 32.00
28	Rear fender inner trim	2	\$ 476.00	\$ 952.00
29	Exhaust assy	1	\$ 797.00	\$ 797.00
30	Exhaust assy gasket	1	\$ 34.00	\$ 34.00
31	Exhaust assy mounting	2	\$ 45.00	\$ 90.00
32	Exhaust assy heatshield	1	\$ 210.60	\$ 210.60
33	Spare wheel panel	1	\$ 854.00	\$ 854.00
34	Spare wheel tools holder	1	\$ 385.00	\$ 385.00
35	Spare wheel top board	1	\$ 303.00	\$ 303.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

36	Spare wheel side board	SL	2	\$ 196.00	\$ 392.00	X
37	Tailgate inner handle	SL	1	\$ 87.00	\$ 87.00	X
38	Tailgate inner trim	SL	1	\$ 645.00	\$ 645.00	X
				Subtotal	\$ 16,733.20	
				List discount	20.00%	
				Total	\$ 13,386.56	

Special nett items						
No.	Parts description		QTY	UNIT PRICE	AMOUNT	
1	Tailgate inner trim clips	AN	8	\$ 4.50	\$ 36.00	X
2	Rear bumper clips	AN	10	\$ 4.50	\$ 45.00	X
3	Reverse camera	SL	1	\$ 450.00	\$ 450.00	X
4	Rear licence plate & frame	SL	1	\$ 55.00	\$ 55.00	X
5	End panel sealant	AN	1	\$ 80.00	\$ 80.00	X
6	Rear windscreen sealant	AN	1	\$ 80.00	\$ 80.00	X
7	Reverse sensor	SL	1	\$ 280.00	\$ 280.00	X
8	Taillamp panel sealant	AN	1	\$ 80.00	\$ 80.00	X
9	End panel top garnish clips	AN	6	\$ 4.50	\$ 27.00	X
10	Rear fender inner trim clips	AN	16	\$ 4.50	\$ 72.00	X
11	Rear boot carpet	SL	1	\$ 250.00	\$ 250.00	X
12	Sundries	AN	1	\$ 50.00	\$ 50.00	X
				Total	\$ 1,505.00	

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00	500
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	150
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	600
4	To remove and refit, straighten, readjust and replace exhaust silencer.	0.75	\$ 150.00	X
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00	1200
6	Supply spray paint material and necessary items to respray tailgate, rear bumper, end panel and other affected area / panel.	7	\$ 1,400.00	600
7	To rust proof all affected portions after repair.	0.5	\$ 100.00	
Total labour			\$ 3,350.00	

Estimate Grand Total	\$ 18,241.56
----------------------	--------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/07/2020 15:15
Date Of Accident	13/07/2020 14:30
Exact Location Of Accident	TOA PAYOH LOR 2 TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML6474J
Insured/Policyholder	
Name Of Registered Owner	PHVILLAGE PTE LTD
Co Reg No	2XXXXXX4E
Email Address	BUSINESS@DRIVERS3.SG
Mobile Phone No	
Alternative Phone No	OFFICE-85965079

Vehicle Particulars

Manufacturer	HONDA
Model	FREED 1.5G HYBRID SENSING AUTO
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110114358-01
Cover Note Number	

Driver

Name of Driver	PERERA EARL CLARENCE
NRIC No	SXXXX311C
Date Of Birth	08/10/1969
Occupation	OUTDOOR
Date Of Driving Pass	18/12/1990
Driving Experience	29 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90102812
Fax Number	
Contact Number	
Email Address	NULITE4U@GMAIL.COM

Address BLK 234A SERANGOON AVE 2 #12-135
Postcode 551234
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : DAUGHTER
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.


Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKS148C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Date of accident: 13.7.2020 Time: 1430 Location: Tea Payoh Lor 2 Toward PIE
 Veh A: SML6474J Veh B: SKS148C No of pax: 2 Weather: Clear/dry Rain/Wet
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SML6474JDate of Accident: 13.7.2020 Time: 1430Place of Accident: Tea Payoh Lor 2 Towards PIE3rd Party: SKS148C

On 13.7.2020 at about 1430, I was driving along Tea Payoh Lor 2 towards PIE. I was pick up my daughter after school. When I reached the stop line, my vehicle was stationary. I waited for the on coming traffic on my right to clear before turning out left into PIE. Out of a sudden, I felt an impact from the rear vehicle. We then exchanged particulars.

☐ Claim OD/TP at Falcon-Air ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address:

nulite4u@gmail.com

Note: Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: