

QRE - (Lsum) JM

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.07.2020

Time: 10:14:46

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305410694
REGN NO : SHC8775J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.12.2015
DATE/TIME IN : 13.07.2020 16:05
ACCIDENT DATE : 13.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	25.00	829.50	dev
0002 04-01-0103-0585-A	LAMP ASSY-RR COMB O/S RH#	1	697.80	25.00	523.35	as
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	25.00	16.50	as
0004 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.50-	50.00	as
0005 04-01-0103-0783-G	BRKT ASSY-RR BUMPER SIDE	1	35.60	25.00	26.70	8m 1419.35
SUB-TOTAL :						1,446.05

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 17-01	CHECK ALL LIGHTING	50.00	30 540.
0003 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
SUB-TOTAL :		730.00	

Amphic 97445746
up
14/7/20 @ 2pm
02 days bumper 450/1600
Rising after repair
Amphic @ Wharf

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: