

**CAB PTE LTD**  
**PAIR ESTIMATE**

Vehicle No.: SHC953P  
Make : MERC  
Model : viano  
DOA : 14/07/2020

Date : 15/07/2020  
Insurance:  
MVA : CHIANG / QBE  
Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	Bumper Assy, Frt			\$1,920.00
1	Bumper Bracket, Frt/LH/RH		\$66.00	\$132.00
1	Bumper Absorber, Frt/LH/RH			\$295.00
1	Bumper Side Beam, Frt/LH/RH			\$26.90
	Radiator Grille Star Logo			\$116.73
1	Radiator Grille			\$1,960.00
1	Bumper Towing Cover, Frt			\$68.00
1	Bumper Grille, Frt/Centre			\$540.00
1	Bumper Grille, Frt/LH/RH		\$44.00	\$88.00
10	Bumper Inner Clip, Frt			\$22.00
1	Fender splashshield lh			\$257.00
1	License Plate Trim Cover, Frt			\$155.00
2	Head Lamp Assy (LH/RH)		\$3,620.00	\$7,240.00
1	Headlamp support panel			\$1,900.00
	<b>SUB TOTAL</b>			<b>\$14,720.63</b>
	<b>LESS 25%</b>			<b>\$3,680.15</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$11,040.48</b>
	Number Plate, Frt (Merc Taxi)			\$50.00
				<b>\$50.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$760.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$60.00
	Towing Charges			✓ \$60.00
	Tuff Kote			\$60.00
	Re-set and Diagnosis			\$550.00
	<b>TOTAL LABOUR</b>			<b>\$2,090.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$13,180.48</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 97445749  
WP  
Lumpsum 15/7/2024pm  
Resurvey after repair  
3 days  
Tanjin e 1khant.wu.  
4179.25  
4/5\$ 3350  
03 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: