

**CITYCAB PTE LTD**  
**REPAIR ESTIMATE**

Vehicle No.: SHC953P  
Make : MERC  
Model : viano  
DOA : 14/07/2020

Date : 15/07/2020  
Insurance:  
MVA : CHIANG  
Admin : *QBE*

Part No.	Parts Description / Labour	Qty	Unit Price	Amount	
1	Bumper Assy, Frt			\$1,920.00	de✓
1	Bumper Bracket, Frt/LH/RH		\$66.00	RH-X \$132.00	LH-de✓
1	Bumper Absorber, Frt/LH/RH			RH-X \$295.00	LH
1	Bumper Side Beam, Frt/LH/RH			\$26.90	?
	Radiator Grille Star Logo			\$116.73	rec✓
1	Radiator Grille			\$1,960.00	can✓
1	Bumper Towing Cover, Frt			\$68.00	?
1	Bumper Grille, Frt/Centre			\$540.00	X
1	Bumper Grille, Frt/LH/RH		\$44.00	\$88.00	X
10	Bumper Inner Clip, Frt			\$22.00	rec✓
1	Fender splashshield lh			\$257.00	th✓
1	License Plate Trim Cover, Frt			\$155.00	dis✓
2	Head Lamp Assy (LH/RH)		\$3,620.00	RH X \$7,240.00	LH-cry
1	Headlamp support panel			\$1,900.00	X
	<b>SUB TOTAL</b>			\$14,720.63	
	<b>LESS 25%</b>			\$3,680.15	
	<b>DISCOUNTED TOTAL</b>			<b>\$11,040.48</b>	
	Number Plate, Frt (Merc Taxi)			\$50.00	Nett
	<b>Labour Charge</b>			<b>\$50.00</b>	
	Panel Beating			\$760.00	320
	Spray Painting Charge			\$600.00	400.
	Wiring Charge			\$60.00	30
	Towing Charges			✓\$60.00	7 spray
	Tuff Kote			\$60.00	X
	Re-set and Diagnosis			\$550.00	250
	<b>TOTAL LABOUR</b>			<b>\$2,090.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$13,180.48</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tanjin 97445749*  
*UP*  
*15/7/2024pm*  
*Resurvey after repair*  
*02 days*  
*Tanjin e 1thank u u.*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Date/Time: 15.07.2020 12:51

Page : 1

Team: ARC Repair TP(CFS0)1

JOB CARD

Sales Order:

JC NO.: 305410956

CUSTOMER

MS CITYCAB PTE LTD  
CUSTOMER NO. 7010070  
RESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65551188  
(P)

*Q.B.13*

REGN NO:  
SHC 953P

MILEAGE

MAKE:  
MERCEDES BENZ

FUEL

E.....1/2.....F

MODEL VIANO CDI 2.2L 14.07.2020 15:45

DATE/TIME IN

YR OF MANU.  
24.10.2013

TARGET DATE

CHASSIS CODE  
WDF63981323804610

COMPLETION DATE/TIME:


COUNT CARD NO.

### JOB DESCRIPTION

Accident Date: 14.07.2020

NATURE: 3P 14.07.2020

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Jgement Slip

Exit Pass

SHC 953P

CHIANG

Vehicle No.:

SHC 953P

Service Advisor

Signature/Date

Name of Service Advisor

To be kept by Security Guard

Date

had to Service Reception upon collection