

Bifrost Auto Pte Ltd

No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No. 201929175W

Vehicle No: SLM 708 G**Model: Honda Civic 1.6L 5MT****Chassis No: JHMFD4520AS200028****Year of manufacturing: 2009**

S/No	Qty	Items	Unit Price	Amount
1	1	RHS front door — <i>Buc</i>	\$	-
2	1	RHS front door hinge <i>X</i>	\$	-
3	1	RHS front door chrome — <i>sch</i>	\$	-
4	2	RHS front door lock <i>X</i>	\$	-
5	1	RHS front door handle <i>X</i>	\$	-
6	1	RHS front door outer molding <i>X</i>	\$	-
7	1	RHS front door inner trim board <i>?</i>	\$	-
8	1	RHS front door power window regulator <i>X</i>	\$	-
9	1	RHS front door power window regulator motor <i>X</i>	\$	-
10	1	RHS rear door — <i>Buc</i>	\$	-
11	1	RHS rear door hinge <i>X</i>	\$	-
12	1	RHS rear door lock <i>X</i>	\$	-
13	1	RHS rear door inner trim board <i>?</i>	\$	-
14	1	RHS rear door chrome — <i>cut</i>	\$	-
15	1	RHS rear door power window regulator <i>?</i>	\$	-
16	1	RHS rear door power window regulator motor <i>X</i>	\$	-
17	1	RHS rear door outer molding — <i>cut</i>	\$	-
18	1	RHS rear absorber <i>X</i>	\$	-
19	1	RHS rear lower arm <i>X</i>	\$	-
20	1	RHS rear upper arm <i>X</i>	\$	-
21	1	RHS rear control arm <i>X</i>	\$	-
22	1	RHS rear knuckle <i>X</i>	\$	-
23	1	RHS rear knuckle hub <i>X</i>	\$	-
24	1	RHS rear wheel bearing <i>X</i>	\$	-
25	1	RHS rear fender — <i>TN</i>	\$	-
26	1	RHS rear fender shield <i>X</i>	\$	-
27	1	RHS rear bumper <i>X</i>	\$	-
28	1	RHS rear bumper retainer <i>X</i>	\$	-
				\$ -
				-20% \$ -
Total for spare parts				\$ -

UKS Auto Consultants hereby notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett						
1	10	Rear bumper clip X	\$	5.00	\$	50.00
2	10	RHS rear fender shield clip /	\$	5.00	\$	50.00
3	1	RHS rear rim Rep sub	\$	900.00	\$	900.00
4	1	RHS rear tyre X	\$	450.00	\$	450.00
5	10	RHS front inner trim board clip X	\$	5.00	\$	50.00
6	10	RHS rear inner trim board clip X	\$	5.00	\$	50.00
			Total for SP		\$	1,550.00
			Sub-Total for Parts :		\$	1,550.00

S/No	Qty	Items	Unit Price	Amount	
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$	1,200.00	800
2		To putty and spray paint on all accident damage parts and other accident	\$	1,000.00	800
3		To check wiring system to facilitate repair and refit the same	\$	60.00	X
4		Apply rust proofing on the adjacent panels	\$	80.00	60
5		To supply under coating / putty on parts replaced	\$	50.00	X
6		To perform water seepage test after repair	\$	120.00	X
7		To remove and refit rear reverse sensor	\$	80.00	X
8		Check and re-adjust wheel alignment	\$	100.00	60
9		To dismantle and transfer door fittings and mechanism to new door/facilitate repair	\$	80.00	60
10		To remove and refit rear bumper reverse sensor	\$	80.00	X
			TOTAL AMOUNT :		\$ 2,850.00
			OVERALL COST:		\$ 4,400.00

6 Days.

Imp Sum Repair.

After repair photos.

Guo Qiang.

16/7/2020.