

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: SLM 708 G
Model: Honda Civic 1.6L 5MT
Chassis No: JHMFD4520AS200028
Year of manufacturing: 2009

S/No	Qty	Items	Unit Price	Amount	
1	1	RHS front door <i>Buc.</i>		\$ 907.50	✓ 808.6
2	1	RHS front door hinge <i>X NN</i>		\$ 48.42	-
3	1	RHS front door chrome <i>sch.</i>		\$ 143.06	✓ 107
4	1	RHS front door lock <i>CUT</i>		\$ 318.42	✓ 250
5	1	RHS front door handle <i>X NN</i>		\$ -	-
6	1	RHS front door outer molding <i>X NN</i>		\$ 58.85	-
7	1	RHS front door inner trim board <i>CRA</i>		\$ 343.20	✓
8	1	RHS front door power window regulator <i>X NN</i>		\$ -	-
9	1	RHS front door power window regulator motor <i>X NN</i>		\$ 612.75	-
10	1	RHS rear door <i>Buc</i>		\$ 847.20	✓
11	1	RHS rear door hinge <i>X NN</i>		\$ 89.30	-
12	1	RHS rear door lock <i>X NN</i>		\$ 318.42	-
13	1	RHS rear door inner trim board <i>CRA</i>		\$ 365.53	✓
14	1	RHS rear door chrome <i>Cut.</i>		\$ 90.40	✓
15	1	RHS rear door power window regulator <i>JM</i>		\$ 314.58	✓
16	1	RHS rear door power window regulator motor <i>X NN</i>		\$ 615.38	-
17	1	RHS rear door outer molding <i>Cut</i>		\$ 67.20	✓
18	1	RHS rear absorber <i>X NN</i>		\$ 930.40	-
19	1	RHS rear lower arm <i>X NN</i>		\$ 824.60	-
20	1	RHS rear upper arm <i>X NN</i>		\$ -	-
21	1	RHS rear control arm <i>X NN</i>		\$ 730.40	-
22	1	RHS rear knuckle <i>X NN</i>		\$ 1690.40	-
23	1	RHS rear knuckle hub <i>X NN</i>		\$ -	-
24	1	RHS rear wheel bearing <i>JM</i>		\$ 813.20	✓ 275.3
25	1	RHS rear fender <i>TN</i>		\$ 2560.40	✓ 1482
26	1	RHS rear fender shield <i>X NN</i>		\$ 79.90	-
27	1	RHS rear bumper <i>X NN</i>		\$ 825.20	-
28	1	RHS rear bumper retainer <i>X NN</i>		\$ 55.60	-
				13,730.41	
				\$ -	4951.11
				-20%	\$ -
Total for spare parts				\$ -	3960.88
				10,984.33	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett								
1	10	Rear bumper clip	X NN	\$	5.00	\$	50.00	
2	10	RHS rear fender shield clip	✓ NEC	\$	5.00	\$	50.00	30
3	1	RHS rear rim	Repair ✓ CUT	\$	900.00	\$	900.00	200
4	1	RHS rear tyre	X NN	\$	450.00	\$	450.00	
5	10	RHS front inner trim board clip	X NN	\$	5.00	\$	50.00	
6	10	RHS rear inner trim board clip	X NN	\$	5.00	\$	50.00	
Total for SP				\$	1,550.00			230
Sub-Total for Parts :				\$	1,550.00			

S/No	Qty	Items	Unit Price	Amount	
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$	1,200.00	1200
2		To putty and spray paint on all accident damage parts and other accident	\$	1,000.00	800
3		To check wiring system to facilitate repair and refit the same	\$	60.00	X NN
4		Apply rust proofing on the adjacent panels	\$	80.00	60
5		To supply under coating / putty on parts replaced	\$	50.00	X NN
6		To perform water seepage test after repair	\$	120.00	X NN
7		To remove and refit rear reverse sensor	\$	80.00	X NN
8		Check and re-adjust wheel alignment	\$	100.00	60
9		To dismantle and transfer door fittings and mechanism to new door/facilitate repair	\$	80.00	60
10		To remove and refit rear bumper reverse sensor	\$	80.00	X NN
TOTAL AMOUNT :				\$	2,850.00
OVERALL COST:				\$	4,400.00
					1980

15,384.33

6170.88

-20%: 3200

6 Days.

Imp Sur repair.

After repair photos.

Geo Q: Amp.

16/7/2020.