

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 23 Jul 2020

Preliminary Advice

Insured Vehicle No	: SMS112G		
TP Vehicle No	: SMC413Y	Accident Date	: 11/07/2020
Make	: MERCEDES-BENZ CLS350	Assignment Date	: 17/07/2020
Date of Inspection	: 16/07/2020	Est. Duration of Repair	:
Inspection At	: Kang Auto Engineering Pte Ltd (HQ) 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear o/s & o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,220.00
Revised Amount	:S\$	5,715.00
Check Items (Estimated)	:S\$	500.00
Total	:S\$	6,215.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP , some parts items are still pending prices.