

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMP 7904 H

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer both headlight control unit and power modules.	S/N \$	800.00	X 500 //
2	To dismantle and renew front bumper and bonnet. Re-organise crash management components. Reinstall all parts removed.	\$	2,400.00	500 /
3	To respray front bumper and bonnet.	\$	2,000.00	1100 /
4	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$	280.00	X nn
* 5	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$	1,200.00	X 500 /
6	To respray rear bumper.	\$	1,000.00	X nn
7	To carry out diagnostic check.	S/N \$	192.00	//
TOTAL LABOUR CHARGES		:	<u>\$ 7,872.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 7904 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER repair <i>XR</i>	\$	1,854.00
2	FRONT BUMPER FIXING PARTS <i>Xsu</i>	\$	343.00
3	FRONT BUMPER GRILLE - CENTRE <i>? cra</i>	\$	195.00 <i>158.60</i>
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Xsu</i> 2	\$	334.00
5	FRONT BUMPER END CAP - LH / RH <i>Xsu</i> 2	\$	68.00
6	FRONT BUMPER SPOILER <i>de</i>	\$	296.00 <i>236.40</i>
7	FRONT BUMPER CLOSING ELEMENT <i>? Xsu</i>	\$	154.00
8	FRONT WHEEL SPOILER - LH / RH <i>Xsu</i> 2	\$	68.00
9	RADIATOR GRILLE <i>cra</i>	\$	1,395.00 <i>1116</i>
10	RADIATOR GRILLE STRIKER PLATE <i>? Xsu</i>	\$	123.00
11	FRONT BUMPER FOAM FILLER PIECE <i>? Xsu</i>	\$	77.00
12	FRONT BUMPER CARRIER <i>? Xsu</i>	\$	679.00
13	FRONT BUMPER COVER <i>Xsu</i>	\$	99.00
14	AIRCON STICKER <i>X n</i>	NEC \$	8.00
15	CAUTION SIGN STICKER <i>X n</i>	NEC \$	14.00
16	HORN - LH LOW TONE <i>Xsu</i>	\$	283.00
17	SIGNAL HORN - RH HIGH TONE <i>Xsu</i>	\$	180.00
18	SPRING SHACKLE - LH / RH <i>X n</i> 2	\$	62.00
19	BONNET repair <i>xt</i>	\$	2,757.00
20	BONNET ATTACHEMENT PARTS <i>X n</i>	\$	163.00
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 9,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 7904 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>nee ✓</i>	3 \$	90.00 <i>70.48 ✓</i>
22	EXTERNAL TEMPERATURE SENSOR <i>X nn</i>	\$	56.00
23	LED HEADLIGHT - LH / RH <i>X snc</i>	2 \$	9,718.00
24	HEADLIGHT MOUNTING - LH / RH <i>X snc</i>	2 \$	234.00
25	LIFT CYLINDER - LH / RH <i>X na</i>	2 \$	282.00
26	LIFT CYLINDER HOSE <i>X nn</i>	\$	175.00
27	RADIATOR AIR GUIDE - LH / RH <i>? xsn</i>	2 <i>pc</i> \$	60.00 <i>23.92 ✓</i>
28	RADIATOR AIR GUIDE - UPPER CENTRE <i>? x snc</i>	\$	22.00
29	FRONT WHEEL COVER - LH / RH <i>nee ✓</i>	2 \$	636.00 <i>508.80 ✓</i>
30	REAR BUMPER <i>X nn</i>	\$	1,164.00
31	REAR BUMPER FIXING PARTS <i>X nn</i>	\$	76.00
32	REAR BUMPER SPOILER - LH <i>cut ✓</i>	\$	281.00 <i>224.80 ✓</i>
33	REAR LIGHT REFLECTOR - LH / RH <i>X nn</i>	2 \$	60.00
34	REAR BUMPER CARRIER <i>? x nn</i>	\$	544.00
35	REAR BUMPER HOLDING STRAP - LH / RH <i>X nn</i>	2 \$	26.00
36	REAR PARKING AID SENSOR - INNER <i>X nn</i>	2	TBC
37	REAR PARKING AID SEAL RING <i>X nn</i>	4 \$	14.00
* 38	REAR WHEEL COVER - LH / RH <i>X nee ✓</i>	2 \$	336.00 <i>268.80 ✓</i>
39	FRONT NO PLATE <i>lt ✓</i>	S/N \$	60.00 <i>4 ✓</i>
40	SUNDIRES <i>? nee ✓</i>	\$	400.00 <i>28.96</i>
TOTAL SPARE PARTS CHARGES		:	\$ 23,386.00
TOTAL LABOUR CHARGES		:	\$ 7,872.00
GRAND TOTAL		:	\$ 31,258.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : RASUL - Hp 90010068
Surveyed Date : 16/07/2020 @ 1005 hrs
Authorised Date :
Excess Cost : 5 days + 3 = TOTAL 8 days
Liability : EXCESS: TPA
Remarks :
Revert
Resurvey before repair

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant