

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Denise

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0494/2020/KK

Date

4-Aug-20

Service Advisor

Glory Tan

Pages

1 OF 1

Regn No

SMP 7904 H

Model No

Audi Q2 1.0 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
Parts			
1	Front lock carrier <i>only 1</i>	\$ 983.00	✓ 786.4
2	Aircon condenser <i>2nd</i>	\$ 545.00	✓ 436
3	Liquid coolant <i>new</i>	\$ 177.00	✓ 141.44
Labours			
1	To remove and renew aircond condenser. To remove and reinstall radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vaccum and regas.	s/n \$ 1,200.00	✓ ✓
2	To renew front lock carrier and align to position.	\$ 2,400.00	1250 ✓
TOTAL		\$ 2,400.00	

For Premium Automobiles Pte Ltd

Adrian Ling
04/08/20
8/8

Authorised Signature

Add 3 days.

Car in

4/8/2020

wip = 41443

Kiam/Hang

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

5 days

Material List for Accident Vehicle Regn No. SMP 7904 H

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
21	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>Me</i>	3	\$ 90.00	
22	EXTERNAL TEMPERATURE SENSOR <i>X</i>		\$ 56.00	
23	LED HEADLIGHT - LH / RH <i>X</i>	2	\$ 9,718.00	
24	HEADLIGHT MOUNTING - LH / RH <i>X</i>	2	\$ 234.00	
25	LIFT CYLINDER - LH / RH <i>X</i>	2	\$ 282.00	
26	LIFT CYLINDER HOSE <i>X</i>		\$ 175.00	
27	RADIATOR AIR GUIDE - LH / RH <i>could</i>	2	\$ 60.00	<i>✓ H/S</i>
28	RADIATOR AIR GUIDE - UPPER CENTRE <i>could</i>		\$ 22.00	<i>✓</i>
29	FRONT WHEEL COVER - LH / RH <i>Me</i>	2	\$ 636.00	
30	REAR BUMPER <i>X</i>		\$ 1,164.00	
31	REAR BUMPER FIXING PARTS <i>X</i>		\$ 76.00	
32	REAR BUMPER SPOILER - LH <i>cut</i>		\$ 281.00	
33	REAR LIGHT REFLECTOR - LH / RH <i>X</i>	2	\$ 60.00	
34	REAR BUMPER CARRIER ?		\$ 544.00	
35	REAR BUMPER HOLDING STRAP - LH / RH <i>X</i>	2	\$ 26.00	
36	REAR PARKING AID SENSOR - INNER <i>X</i>	2	TBC	
37	REAR PARKING AID SEAL RING <i>X</i>	4	\$ 14.00	
38	REAR WHEEL COVER - LH / RH <i>X</i> <i>new</i>	2	\$ 336.00	<i>✓ H/S</i>
39	FRONT NO PLATE	S/N	\$ 60.00	<i>4</i>
40	SUNDIRES ?		\$ 400.00	
TOTAL SPARE PARTS CHARGES		:	\$ 23,386.00	
TOTAL LABOUR CHARGES		:	\$ 7,872.00	
GRAND TOTAL		:	\$ 31,258.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (O) = Not approved
Spare parts are Special Nett.Resurveyed
04/08/20 Adm 2 C
H/S

+ SUPP

444