

Not Assembled
Running By paint

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD 5199L

AAD2007-056

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

16 JUL 2020

SHD 5199L
JTDKB3FU103076615
TOYOTA
PRIUS
13.7.2020
FWD
01-11-18

PART
1 PANEL SUB-ASSY, FRONT DOOR, LH
1 TAPE, BLACK OUT, NO.1 FRT LH
1 TAPE, BLACK OUT, NO.2 FRT LH
1 TAPE, BLACK OUT, NO.3 FRT LH
1 PANEL SUB-ASSY, REAR DOOR, LH
1 LOCK ASSY, REAR DOOR WITH MOTOR, LH
1 HINGE ASSY, REAR DOOR, UPPER LH
1 HINGE ASSY, REAR DOOR, LOWER LH
1 CHECK ASSY, REAR DOOR, LH
1 MOULDING ASSY, REAR DOOR BELT, LH
1 WEATHERSTRIP, REAR DOOR, NO.3 LH
1 TAPE, BLACK OUT, NO.1 REAR LH
1 TAPE, BLACK OUT, NO.2 REAR LH
1 TAPE, BLACK OUT, NO.3 REAR LH
1 MOULDING ASSY, BODY ROCKER PANEL, LH

	LIST	
\$	R 1,300.70	✓ X
\$	nn 13.30	X
\$	nn 43.50	X
\$	nn 26.30	X
\$	R 1,294.90	✓
\$	R 561.90	X
\$	SVC 98.90	X
\$	SVC 87.10	X
\$	nn 183.80	X
\$	nn 113.50	X
\$	nn 36.20	✓
\$	nn 21.90	✓
\$	nn 34.90	✓
\$	nn 15.40	✓
\$	R 594.80	X
TOTAL	\$ 4,427.10	
25%	\$ 1,106.78	
	\$ 3,320.33	

Special Nett
1 FRONT DOOR STICKER "TRANS-CAB"
1 REAR DOOR STICKER "6555-3333"
1SET ROCKER PANEL MOULDING CLIP
1 DOOR HINGE SCREW
1 DOOR CHECK SCREW

\$	nn 100.00	60.00
\$	nn 100.00	60.00
\$	nn 55.00	X
\$	nn 45.00	X
\$	nn 45.00	X
TOTAL	\$ 345.00	

TOTAL PARTS \$ 3,665.33

LABOUR
To Check Electrical Lighting Concerned.

\$ 170.00 20%

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No.: 6287 6666 Fax No.: 6257 1330
CO/GST Reg. No. 201019626G
SHD 5199L

AAD2007-056

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	2001
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	170.00	301
To transfer of front door fittings, attachment and perform water seepage test.	\$	nn 170.00	601 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
To transfer of rear door fittings, attachment and perform water seepage test.	\$	170.00	601
TOTAL	\$	10,060.00	

Over All Total \$ 13,725.33

(PART-BY-PART) Repair Days 15 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify
the Repairer of the following:
• To survey before/after spray painting
• To display damaged part(s) during resurvey
• Part prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature: _____
Date: _____

Scanned with CamScanner