



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1458S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL, SIDE:R6, FOR MAN A22 BUS	TO REPAIR SEE LABOUR	1,776.80	-
1	PANEL, SIDE:R7, FOR MAN A22 BUS	TO REPAIR SEE LABOUR	885.50	-
			2,662.30	-
	<u>SPECIAL NETT ITEMS</u>			
1	STICKER SMRT (SN)	NECESSARY	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO REPAIR RH PORTION. INCLUSIVE OF THE REPAIR OF PANEL, SIDE:R6, FOR MAN A22 BUS AND PANEL, SIDE:R7, FOR MAN A22 BUS.		1,590.00	1,060.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		878.00	708.00
			2,468.00	1,768.00
	GRAND TOTAL		5,330.30	1,968.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,550.00

Report Ref No. NS/INC20007385/Qvf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.