





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/08/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB26L
Case Reference Number	BUS/07/20/1011
Registration Date	11/11/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Tan Kian Soon
Type of Accident	Side Swipe
Accident Date and Time	10/7/2020 4:40 PM
Accident Reported Date and Time	10/7/2020 5:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107758
Special Instruction to ARC,if any	SMB26L-RIGHT REAR PORTION SMS1452T (TP) INSURED WITH NTUC
Prepared Date and Time	14/7/2020 4:47 PM
Chassis Number	WEB63442021000087
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$942.00	\$772.00
Total Spare Part Cost	\$160.00	\$160.00
Total Other Cost	\$0.00	(\$366.40)
TOTAL COST	\$2,427.00	\$1,625.60
Lump Sum Total	\$2,450.00	\$1,650.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	14/07/2020 4:58 PM	15/07/2020 2:33 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/08/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,325.00				\$1,060.00		
Total Labour			\$1,325.00				\$1,060.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$942.00				\$772.00		
Total Spray Painting & Panel Beating			\$942.00				\$772.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$366.40)		
Total Other Costs			\$0.00				(\$366.40)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	Replace
6010227	BODY RH	5019	PANEL,SKIRT:R4,FOR MB OC500 BUS	1.00	\$1,442.10	100.00	\$0.00	Repair	Repair
6010229	BODY RH	5021	PANEL,SKIRT:R6,FOR MB OC500 BUS	1.00	\$518.20	100.00	\$0.00	Repair	Repair
6010230	BODY RH	5022	PANEL,SKIRT:R7,FOR MB OC500 BUS	1.00	\$880.50	100.00	\$0.00	Repair	Repair
6010231	BODY RH	5023	PANEL,SKIRT:R8,FOR MB OC500 BUS	1.00	\$338.10	100.00	\$0.00	Repair	Repair
6010232	BODY RH	5024	PANEL,SKIRT:R9,FOR MB OC500 BUS	1.00	\$307.10	100.00	\$0.00	Repair	Repair
6010234	BODY RH	5026	PANEL,SKIRT:R11,FOR MB OC500 BUS	1.00	\$642.80	100.00	\$0.00	Repair	Repair
Total					\$4,328.80		\$200.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3 days

45
\$1,650

200
1,060
772

2,032
- 20%

1,625.60