



Case Details

Case Reference Number :
TAX/07/20/2025

Type of Repair : Accident Repair

Vehicle Registration Number :
SHF130G

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-12061-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 14/07/2020 10:30 AM

Vehicle Age(In Months) : 32

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Surveyor Approval					Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92 317.93	Replace	1	317.92	Replace	✓ / CRU	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ / Nec	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ / Nec	
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓ / Nec	
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	✓ X Svc	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✓ X Svc	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ / Nec	

Total Spare Part Cost 10,574.87

Surveyor Total 2,997.05

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,459.90

Final Sur Total 2,397.64

15/01/2020

https://vacswed.smr.com.sg/Estimation.aspx

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace	✓ BR
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	1	4.30	4.30	25.00	3.22	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	✓ MIS
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72 418.73	Replace	1	418.72	Replace	✓ CR4
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	✓ Nec
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	✓ CR4
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	1	175.72	Replace	✓ cut
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	1	63.90	Replace	✓ CRA
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,569.70	1,569.70	25.00	1,177.28	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	27.90	25.00	20.92	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			SEALANT W/SCREEN	2	37.00	74.00	0.00	74.00	Replace	0	0	Not Give	✓ X Svc

Total Spare Part Cost 10,574.87

Surveyor Total 2,997.05

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,459.90

Final Sur Total 2,397.64

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disa(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	725.90	25.00	544.42	Replace	1	544.42 544.43	Replace	✓ / BR
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	27.90	25.00	20.92	Replace	1	20.92 20.93	Replace	✓ / NEC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , LH	1	29.90	29.90	25.00	22.42	Replace	1	22.42 22.43	Replace	✓ / NEC
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , RH	1	29.90	29.90	25.00	22.42	Replace	1	22.42 22.43	Replace	✓ / Nec
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	1	14.77	Replace	✓ / Nec
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ / Nec
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72 34.73	Replace	✓ / NEC
One Time Key In	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22 39.23	Replace	✓ / NEC
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22 39.23	Replace	✓ / Nec
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ / Nec
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ / Nec
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	0	Repair	✓ X R
One Time Key In	Main			LAMP SET, STOP CENTER	1	186.50	186.50	10.00	167.85	Replace	0	0	Not Give	✓ X SW
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Give	✓ SWC

Total Spare Part Cost 10,574.87

Surveyor Total 2,997.05

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,459.90

Final Sur Total 2,397.64

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			EXTENSION, REAR FLOOR SIDE PANEL, LH	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			BOX, DECK FLOOR, LH	1	303.40	303.40	25.00	227.55	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	344.70	25.00	258.52	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	✓ / CRU.
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	1	40.50	Replace	✓ / SCR
One Time Key In	Main			TROUGH, BACK DOOR, LH	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			LINER, REAR FENDER, LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	✓ X SVC
Total Spare Part Cost									10,574.87	Surveyor Total 2,997.05				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									8,459.90	Final Sur Total 2,397.64				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH REAR PORTION	1,014.00	400	✓
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	/
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	100	/
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
4	Main	TO RESPRAY TAIL GATE	378.00	0	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	/
6	Main	TO RESPRAY REAR SPOILER	180.00	100	/
7	Main	TO RESPRAY REAR PANEL	180.00	0	
8	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
9	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
10	Main	TO RESPRAY REAR FENDER LH	378.00	0	
11	Main	TO RESPRAY RIM	180.00	0	
Total:			2,574.00	500.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	/
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	475.00	125	/
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	/
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
Total:			1,975.00	305.00	

15/07/2020

https://vacsweb.smrt.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
10	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100	
11	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
12	Main	TO REPLACE SUNDRY PARTS	100.00	0	
13	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,975.00	305.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,459.90	2,397.64
Total Labour Cost	1,014.00	400.00
Total Spray Painting	2,574.00	500.00
Other	1,975.00	305.00
Overall Total	14,022.90	3,602.64
Lump Sum Repair Option		☒
Lump Sum Total	14,000.00	3,600.00
Surveyor Approved Amount		3,600.00
No of Repair Days*	8	3 <i>3 days</i>
Remarks	-	L/S, after paint photo

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

15/07/2020