

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 41593

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0498/2020/NS
Date	:	16-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Annie Yeo Wei Zhen
Address	:	171A Edgedale Plains Singapore 821171
Telephone	:	HP +65 93372266
Type of Claim	:	Own Damage Claim
Policy No.	:	1900009384
Vehicle No	:	SGW 8805 M
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Jan-19
Engine No	:	CHZ C26014
Chassis No	:	WAUZZZ8V7K1013257
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	5-Jul-20
Place of Accident	:	Blk 723 Tampines St 72 Near Loading Bay

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGW 8805 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To dismantle and reinstall rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 350.00 ✓	
2	To dismantle and reinstall front bumper. To renew rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 ✓	{ Remove bumper Remove fender Repair door
3	To respray rhs front fender and rhs front door.	\$ 2,000.00 1100 ✓	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
SUB TOTAL LABOUR CHARGES		: <u>\$ 4,642.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 8805 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH <i>Dented</i>	\$ 841.00	✓ 672.80
2	FRONT FENDER ATTACHMENT PARTS ?	\$ 71.00	✗ NN
3	FRONT FENDER BRACKET - RH	\$ 27.00	✗
4	FRONT FENDER BRACKET - RH <i>new</i>	\$ 38.00	✗
5	FRONT FENDER BRACE	\$ 95.00	✗
6	FRONT FENDER INSULATION - RH ?	\$ 42.00	✗ NN
7	FRONT FENDER CLOSING ELEMENT - RH <i>new</i>	\$ 33.00	✗
8	WHEEL HOUSING LINER - RH <i>new</i>	\$ 167.00	✗
9	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 88.00	✗
10	SUNDRIES ?	\$ 200.00	✓ 15.36 NEC
TOTAL SPARE PARTS CHARGES		:	\$ 1,602.00
TOTAL LABOUR CHARGES		:	\$ 4,642.00
GRAND TOTAL		:	\$ 6,244.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax 6841 1183

Telefax

Name

: Adrian Ly

Surveyed Date

: 17/07/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 03849

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant