

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE WEN FEN
30 AH HOOD ROAD
#06-02
329976

ATTN:

Your Ref No: SDM7600G
Claim Type: Third Party
Accident Date: 13/07/2020
TP Veh Reg No: SGJ8490E

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate No: MCS1900306
Date: 15 Jul 2020
Policy No: P10102499R01
Veh Reg No: SDM7600G
Make/Model: TOYOTA HARRIER 2.0
PREMIUM AT AIRBAG
2WD

Estimate Repair Cost to Vehicle No :SDM7600G

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER / Re .	1 PC	1,605.90	1381
2 REAR BUMPER SIDE RETAINER LH / Re .	1 PC	69.70	✓
3 REAR BUMPER LOWER GARNISH / Re .	1 PC	411.67	389
4 REAR BUMPER SPONGE X NN	1 PC	127.80	X
5 REAR BUMPER CLIP / Re .	10 PC	39.90	30
		2,254.97	1869.7
	Less 25%	563.74	1,691.23
Special Nett			1402.27
6 REVERSE SENSOR X NN .	1 SET	220.00	
		220.00	220.00
LABOUR			
7 TO CHECK WIRING AND INSTALL REVERSE SENSOR	1 PC	30.00	✓
8 TO DISMANTLE AND INSTALL RR END PANEL INNER TRIM BOARD AND COVER	1 PC	60.00	30
9 TO DISMANTLE AND INSTALL DAMAGE PARTS, TO KNOCK AND REPAIR TAIL END PANEL AND TO REFIT LISTED PARTS BACK SAME	1 PC	500.00	250 .
10 TO SPRAY RR BUMPER, TAIL END PANEL	1 PC	500.00	300 610
		1,090.00	1,090.00
Total			S\$ 3,001.23
Add GST @ 7%			210.09
Total Amount Payable			S\$ 3,211.32

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWO HUNDRED ELEVEN AND CENTS THIRTY TWO ONLY

3 Days .
part by part .
before paint photos .
Eric Chiang - 82880282
17/7/2020 .

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

2012.27