



Not Authored
LKK
Take photo before repair.
3 days
22/7/20

TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

22-Jul-201500-01
LKK
EUROKARS GROUP

FIRST CAPITAL INSURANCE LTD		NAME : Mr Tan Lark Wang		WIP : 31088	
36 ROBINSON ROAD		ADDRESS : 27 Kensington Park Road		EXCESS :	
#16-01 CITY HOUSE		Singapore 557274		DATE: 15-Jul-20	
SINGAPORE 068877		TEL : 96644831			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SW98Y	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6CC1071H0111373	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	BIANTE	DATE REG.:	31-Oct-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	DIS ✓ 1	MC605-50-031CBB		\$ 1,074.30
2	RETAINER LHS	Self ✓ 1	MC273-50-0U1D		\$ 40.80
3	BRACKET LHS, FRONT BUMPER	? 1	MC467-50-161A		\$ 133.50
4	STRIPE'G' LHS, FRONT BUMPER	Rec ✓ 1	MC467-50-887		\$ 81.50
5	STRIPE'G' RHS, FRONT BUMPER	Rec ✓ 1	MC467-50-877		\$ 81.50
6	CHROME LHS	11 X 1	MC467-50-7K1		\$ 570.90
7	FASTENER, FRONT BUMPER	Rec ✓ 1	MGD7A-50-EA1		\$ 3.20
8	CLIP, FRONT BUMPER	Rec ✓ 10	MC274-50-133		\$ 37.00
9	CLIP, FRONT BUMPER	Rec ✓ 2	MFB01-50-133C		\$ 8.00
10	SEAL RUBBER, FRONT BUMPER	Rec ✓ 2	MC467-50-2G2		\$ 85.00
11	COVER LHS, FOGLAMP	11 X 1	MC605-50-C21A		\$ 186.10
12	FOGLAMP LHS	11 X 1	MC461-51-690		\$ 463.70
13	HEADLAMP LHS	scr/cnc ✓ 1	MC274-51-041D		\$ 2,744.40
14	CLIP, HEADLAMP	11 X 5	MC273-50-133A		\$ 50.50
15	RIVET, HEADLAMP	Rec ✓ 1	MB092-51-833		\$ 3.50
16	FASTENER, GARNISH	11 X 2	MC235-51-081		\$ 16.40
17	FRONT FENDER LHS	2 X 1	MC275-52-211B		\$ 382.20
18	MUDGUARD LHS	11 X 1	MC273-56-140C		\$ 181.10
19	FASTENER, MUDGUARD	11 X 15	MB45A-56-146A		\$ 45.00
20	FASTENER, FRONT GRILLE	11 X 2	MD350-50-E21		\$ 22.20
21	FASTENER, FRONT GRILLE	11 X 2	MB041-68-865 02		\$ 9.80
TOTAL PARTS					\$ 6,220.60
TOTAL PARTS COST					\$ 6,220.60
Labour Description					

1	MZ-BR-FRONT1	TO REPLACE FRONT BUMPER. REPAIR FRONT FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,320.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER LH.	945	\$ 1,260.00
3	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	14X	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	Net 20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 3,530.00
TOTAL PARTS	\$ -	\$ 6,220.60
TOTAL	\$ -	\$ 9,750.60
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: