



Case Details

Case Reference Number : TAX/07/20/2016
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB591E

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-12021-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 08/07/2020 09:00 AM
 Vehicle Age(In Months) : 70

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	0	0	Not Give	✓ Xsve
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace	✓ / DD
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ / Nec
One Time Key In	Main			DOOR HINGE UPPER RR/RH	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	✓ Xsve
One Time Key In	Main			DOOR HINGE LOWER RR/RH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✓ Xsve
One Time Key In	Main			DOOR BELT RR/RH	1	69.20	69.20	25.00	51.90	Replace	0	0	Not Give	✓ Xsve
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	✓ Xsve
One Time Key In	Main			DOOR WEATHER STRIP RR/RH	1	171.20	171.20	25.00	128.40	Replace	0	0	Not Give	✓ Xsve
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	670.80	Replace	✓ / pp

Total Spare Part Cost 3,293.64

Surveyor Total 1,506.68

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 2,634.91

Final Sur Total 1,205.34

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ / NEC
One Time Key In	Main			DOOR BELT FRT/RH	1	69.20	69.20	25.00	51.90	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			DOOR LOCK FRT/RH	1	575.80	575.80	25.00	431.85	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			DOOR WEATHER STRIP FRT/RH	1	171.20	171.20	25.00	128.40	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PILLAR, CTR BODY	1	307.70	307.70	25.00	230.77	Replace	0	0	Not Give	✓ X SVC
Total Spare Part Cost									3,293.64	Surveyor Total			1,506.68	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									2,634.91	Final Sur Total			1,205.34	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	400	✓
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	✓
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
3	Main	TO RESPRAY CENTRE PILLAR RH	180.00	0	
4	Main	TO RESPRAY RH REAR DOOR	378.00	200	✓
Total:			1,116.00	400.00	

Other Cost Detail

13/07/2020

https://vacswed.smrt.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO TRANSFER DOOR MECHANISM	240.00	100	/
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	/
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO WASH AND VACUUM	60.00	0	
7	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
Total:			1,130.00	140.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,634.91	1,205.34
Total Labour Cost	845.00	400.00
Total Spray Painting	1,116.00	400.00
Other	1,130.00	140.00
Overall Total	5,725.91	2,145.34
Lump Sum Repair Option		☒
Lump Sum Total	5,750.00	2,150.00
Surveyor Approved Amount		2,150.00
No of Repair Days*	6	3 <i>3 days</i>
Remarks	-	L/S, after paint photo
Surveyor Name		Sun Pin (LKK)
Signature	<i>g</i>	<i>[Signature]</i>
Survey Date	13/07/2020	