

Section A - Accident Details

Registration Number	SHB591E
Case Reference Number	TAX/07/20/2016
Registration Date	12/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG KIM THONG
Type of Accident	Others
Accident Date and Time	8/7/2020 5:00 PM
Accident Reported Date and Time	9/7/2020 4:12 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107507
Special Instruction to ARC, if any	TP / RIGHT PORTION
Prepared Date and Time	11/7/2020 8:19 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$3,072.74	\$1,643.17
Total Other Cost	\$1,130.00	\$140.00
TOTAL COST	\$6,163.74	\$2,583.17
Lump Sum Total	\$6,150.00	\$2,600.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	15/07/2020 9:22 AM	15/07/2020 9:17 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	L/S, after paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2007-0380	Invoice Number	
Quotation Date	28.07.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY CENTRE PILLAR RH	\$180.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$100.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
Total Other Costs	\$1,130.00	\$140.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		75851-47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X SVC
		67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	DD
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	NEC
		68750-20122	DOOR HINGE UPPER RR/RH	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X SVC
		68770-52031	DOOR HINGE LOWER RR/RH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X SVC
		75730-47021	DOOR BELT RR/RH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given	X SVC
		68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X SVC
		67871-47030	DOOR WEATHER STRIP RR/RH	0.00	\$171.20	0.00	\$0.00	Replace	Not Given	X SVC
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	DD
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	NEC
		75710-47021	DOOR BELT FRT/RH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given	X SVC
		69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given	X SVC
		69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Not Given	X SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/07/2020
User ID : PohSuan

		67861-47030	DOOR WEATHER STRIP FRT/RH	0.00	\$171.20	0.00	\$0.00	Replace	Not Given X
		61311-47030	PILLAR, CTR BODY	0.00	\$307.70	0.00	\$0.00	Replace	Not Given X
Total					\$4,351.50		\$1,506.68		

SVC
SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		68750-20122	DOOR HINGE UPPER RR/RH	1.00	\$81.70	25.00	\$61.28	Replace	Replace
		68770-52031	DOOR HINGE LOWER RR/RH	1.00	\$72.20	25.00	\$54.15	Replace	Replace
		69030-47070	DOOR LOCK FRT/RH	1.00	\$575.80	25.00	\$431.85	Replace	Replace
Total					729.70		547.28		

BT
BT
CRA

2053.96 /

- 207 /

1643.17 /

+ 400.00 /

+ 540.00 /

2583.17 /

415 \$2600/- /

3 days