

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 41997

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0501/2020/NS
Date : 18-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Lim Chia Nie
Address : 103 Victoria Park Grove
Singapore 266186
Telephone : +(HP) 90282552
Type of Claim : Own Damage Claim
Policy No. : 1800109579-01
Vehicle No : **SMF 103 B**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : Sep-18
Engine No : CYR 069824
Chassis No : WAUZZZ4M3JD060912
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Jul-20
Place of Accident : Hillcrest Road Towards Greenwood and NJC Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Shirley.

15/8/84

Estimated Labour Charges for Accident Vehicle SMF 103 B

| S/N | Nature of Jobs | Estimated Charges | Surveyor's Recommendations |
|-----------------------------|---|------------------------------|----------------------------|
| 1 | To remove and transfer/reinstall front bumper wire harness for front parking aid system. | S/N \$ 280.00 ✓ | |
| 2 | To remove and transfer rhs headlight control unit, power module and electrical fans for Led and connectors. | S/N \$ 550.00 250 | |
| 3 | To dismantle and reinstall rhs front door panel trim. To remove and reinstall rhs wing mirror assy. | S/N \$ 450.00 ✓ | |
| 4 | To dismantle and renew front bumper and rhs front fender. Re-organise crash management components. Reinstall all parts removed. | \$ 2,700.00 1200 | 600 x 2 = 1200 |
| 5 | To respray front bumper, rhs front fender and rhs front door. | \$ 3,500.00 1800 | 600 x 3 = 1800 |
| 6 | To carry out diagnostic check. | S/N \$ 192.00 ✓ | |
| TOTAL LABOUR CHARGES | | : \$ 7,672.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel. 6366 2323 Fax. 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 103 B

| S/N Parts Description | | Damage Parts & Prices | |
|-------------------------------|---|-----------------------|------------|
| S/N | Parts Description | S/Nett | Remarks |
| 1 | FRONT BUMPER <i>Delnd</i> | \$ 2,434.00 | ✓ 1,947.20 |
| 2 | FRONT BUMPER FIXING PARTS <i>see n</i> | \$ 442.00 | ✗ |
| 3 | FRONT BUMPER TOWING EYE COVER <i>then cut</i> | \$ 39.00 | ✗ ✓ 30.88 |
| 4 | FRONT BUMPER AIR GUIDE - RH <i>excluded</i> | \$ 66.00 | ? ✓ 52.40 |
| 5 | FRONT BUMPER END CAP - RH <i>excluded</i> | \$ 35.00 | ? ✓ 27.84 |
| 6 | FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>then</i> | \$ 273.00 | ✗ |
| 7 | FRONT BUMPER GRILLE - LOWER CENTRE <i>then</i> | \$ 203.00 | ✗ |
| 8 | FRONT BUMPER UNDERRUN BAR <i>then</i> | \$ 798.00 | ✗ |
| 9 | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>then</i> | \$ 208.00 | ✗ |
| 10 | FRONT BUMPER FRONT SPOILER - RH <i>Delnd</i> | \$ 137.00 | ✓ 109.60 |
| 11 | FRONT SPOILER TRIM - RH OUTER <i>Not nec</i> | \$ 43.00 | ? ✗ |
| 12 | RADIATOR GRILLE <i>?</i> | \$ 2,445.00 | ✗ |
| 13 | RADIATOR GRILLE COVER <i>then</i> | \$ 72.00 | ✗ |
| 14 | RADIATOR GRILLE INNER COVER | \$ 61.00 | ✗ |
| 15 | FRONT BUMPER AIR GUIDE GRILLE <i>cut</i> | \$ 294.00 | ✓ 234.80 |
| 16 | FRONT BUMPER END CAP - RH <i>Delnd</i> | \$ 33.00 | ? ✓ 26.32 |
| 17 | SPOILER DEFLECTOR - RH INNER <i>Not nec</i> | \$ 57.00 | ? ✗ |
| 18 | FRONT BUMPER FOAM FILLER PIECE <i>?</i> | \$ 170.00 | ✗ |
| 19 | FRONT BUMPER CARRIER <i>then</i> | \$ 858.00 | ✗ |
| 20 | FRONT BUMPER SUPPORT - LH / RH | 2 \$ 72.00 | ✗ |
| SUB TOTAL SPARE PARTS CHARGES | | : <u>\$ 8,740.00</u> | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 103 B

| S/N | Parts Description | Damage Parts & Prices | |
|---------------------------|--|-----------------------|-------------|
| | | S/Nett | Remarks |
| 21 | FRONT BUMPER GUIDE SECTION - RH Not in DMG | \$ 44.00 + ✓ | 34.48 |
| 22 | FRONT PARKING AID SENSOR - INNER / OUTER Not in | TBC + | |
| 23 | FRONT PARKING AID SEAL RING Not in | 4 \$ 14.00 + | |
| 24 | FRONT FENDER - RH Not in | \$ 1,602.00 X | |
| 25 | FRONT FENDER ATTACHMENT PARTS Not in | \$ 75.00 - X | |
| 26 | FRONT FENDER BRACE Not in | \$ 100.00 ? ✓ | 79.92 |
| 27 | FRONT FENDER BRACKET - RH Not in | \$ 64.00 ? X | |
| 28 | LED HEADLIGHT Not in | \$ 9,813.00 ✓ | 7,850.40 |
| 29 | LIFT CYLINDER - RH Not in | \$ 196.00 X | |
| 30 | FRONT DOOR COVER - RH Not in | \$ 447.00 ✓ X | |
| 31 | FRONT WHEEL COVER - LH / RH Not in | 2 \$ 654.00 ✓ | 522.40 |
| 32 | WHEEL HOUSING LINER - RH Not in | \$ 237.00 + | |
| 33 | WHEEL HOUSING LINER - RH REAR Not in | \$ 237.00 + | |
| 34 | HEADLIGHT MOUNTING - RH Not in | \$ 117.00 + ✓ | 93.60 |
| 35 | FRONT NO PLATE Not in | S/N \$ 60.00 + | |
| 36 | SUNDRIES Not in | \$ 300.00 ? X | |
| TOTAL SPARE PARTS CHARGES | | : | \$22,700.00 |
| TOTAL LABOUR CHARGES | | : | \$ 7,672.00 |
| GRAND TOTAL | | : | \$30,372.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

05 Days -
H.S.

26/11/2020 @ 10:43 AM CHECKED
WITH ADRIAN VIA PHONE CALL.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj
31/07/20

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant