LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur Date: 22 Jul 2020

Preliminary Advice

Vehicle No : SMF103B Accident Date : 17/07/2020 Make : AUDI Q7 Policy No. : 1800109579 Assignment Date : 20/07/2020 **Excess** : S\$500.00 Date of Inspection : 21/07/2020 Est. Duration of Repair : 5 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,372.00
Revised Amount	:S\$	17,951.00
Check Items (Estimated)	:S\$	773.00
Total	:S\$	18,724.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 192,000.00

 COE / PARF Rebate
 :S\$ 85,094.00

Salvage Value :S\$

Margin for Repair :S\$ 106,906.00

Remarks

X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :