

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 41997

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0501/2020/NS
Date : 18-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Lim Chia Nie
Address : 103 Victoria Park Grove
Singapore 266186
Telephone : +(HP) 90282552
Type of Claim : Own Damage Claim
Policy No. : 1800109579-01
Vehicle No : **SMF 103 B**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : Sep-18
Engine No : CYR 069824
Chassis No : WAUZZZ4M3JD060912
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Jul-20
Place of Accident : Hillcrest Road Towards Greenwood and NJC Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 103 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00 ✓	
2	To remove and transfer rhs headlight control unit, power module and electrical fans for Led and connectors.	S/N \$ 550.00 250	
3	To dismantle and reinstall rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 450.00 ✓	
4	To dismantle and renew front bumper and rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,700.00 1200	600 x 2 = 1200
5	To respray front bumper, rhs front fender and rhs front door.	\$ 3,500.00 1800	600 x 3 = 1800
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,672.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 103 B

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Deland</i>	\$ 2,434.00 ✓	1,947.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 442.00 ✗	
3	FRONT BUMPER TOWING EYE COVER <i>new</i>	\$ 39.00 ✗ ✓	30.88
4	FRONT BUMPER AIR GUIDE - RH ?	\$ 66.00 ? ✓	52.40
5	FRONT BUMPER END CAP - RH ?	\$ 35.00 ? ✓	27.84
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$ 273.00 ✗	
7	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	\$ 203.00 ✗	
8	FRONT BUMPER UNDERRUN BAR <i>new</i>	\$ 798.00 ✗	
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 208.00 ✗	
10	FRONT BUMPER FRONT SPOILER - RH <i>Deland</i>	\$ 137.00 ✓	109.60
11	FRONT SPOILER TRIM - RH OUTER ?	\$ 43.00 ? ✗	
12	RADIATOR GRILLE <i>new</i>	\$ 2,445.00 ✗	
13	RADIATOR GRILLE COVER <i>new</i>	\$ 72.00 ✗	
14	RADIATOR GRILLE INNER COVER	\$ 61.00 ✗	
15	FRONT BUMPER AIR GUIDE GRILLE <i>ut</i>	\$ 294.00 ✓	234.80
16	FRONT BUMPER END CAP - RH ?	\$ 33.00 ? ✓	26.32
17	SPOILER DEFLECTOR - RH INNER ?	\$ 57.00 ? ✗	
18	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 170.00 ✗	
19	FRONT BUMPER CARRIER	\$ 858.00 ✗	
20	FRONT BUMPER SUPPORT - LH / RH	2 \$ 72.00 ✗	
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,740.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 103 B

S/N	Parts Description			Damage Parts & Prices	
				S/Nett	Remarks
21	FRONT BUMPER GUIDE SECTION - RH	new	\$	44.00	+✓ 34.48
22	FRONT PARKING AID SENSOR - INNER / OUTER	new 2		TBC	+
23	FRONT PARKING AID SEAL RING	Not in	4 \$	14.00	+
24	FRONT FENDER - RH	Rep's	\$	1,602.00	X
25	FRONT FENDER ATTACHMENT PARTS	?	\$	75.00	? X
26	FRONT FENDER BRACE	?	\$	100.00	? ✓ 79.92
27	FRONT FENDER BRACKET - RH	?	\$	64.00	? X
28	LED HEADLIGHT	crushed	\$	9,813.00	✓ 7,850.40
29	LIFT CYLINDER - RH	Not in	\$	196.00	X
30	FRONT DOOR COVER - RH	new	\$	447.00	✓ X
31	FRONT WHEEL COVER - LH / RH	new	2 \$	654.00	✓ 522.40
32	WHEEL HOUSING LINER - RH	} new	\$	237.00	+
33	WHEEL HOUSING LINER - RH REAR		\$	237.00	+
34	HEADLIGHT MOUNTING - RH		\$	117.00	+✓ 93.60
35	FRONT NO PLATE	Not in	S/N \$	60.00	+
36	SUNDRIES	?	\$	300.00	? X
TOTAL SPARE PARTS CHARGES			:	\$22,700.00	
TOTAL LABOUR CHARGES			:	\$ 7,672.00	
GRAND TOTAL			:	\$30,372.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Lj
31/07/20

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant