

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007441/BVF3E2

Date: 12/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3073721901
Claimant Vehicle No :	SLH939H	Insured Vehicle No :	SKD5434Y
Date of Loss:	17/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202476/C01/TANGHL2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH939H	Engine No:	B4164T1138068
Make & Model:	VOLVO S60, 1.6 T4 (A)	Chassis No:	YV1FS48HBD2230627
Reg. Date:	31/07/2013 (Man. Year: 2013)	Odometer:	165678 km
Colour:	White		
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,260.59	7,186.25	9,074.34	55.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	2,660.00	2,290.00	46.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,210.59	9,846.25	11,364.34	53.58
Approved Total (Overridden) (S\$)		5,550.00		
Nett Amount (S\$)	21,210.59	5,550.00	15,660.59	73.83

INSPECTION

Date of Assignment:	10/09/2020	
Date Inspected:	20/07/2020	Inspected At:
		Team Autopro Pte Ltd - Sin Ming (HQ)
		160 SIN MING DR
		#01-14 SIN MING AUTO CITY
		SINGAPORE 575722
Estimated Period of Repair:	8.0 days	

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2020)

Parts: 143 VOLVO S60 1.6 T4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH939H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	981.95 FL	*- FL
2	1		*FRONT FENDER INNER COWLING LH	Not Damaged	214.58 FL	*- FL
3	1		*FRONT DOOR LH	Dented	2,126.30 FL	*2,126.30 FL
4	1		*FRONT DOOR OUTER HANDLE LH	Cut	183.90 FL	*183.90 FL
5	1		*FRONT DOOR WEATHERSTRIP LH	Not Damaged	286.50 FL	*- FL
6	1		*FRONT DOOR REGULATOR LH	Bent	682.50 FL	*682.50 FL
7	1		*FRONT DOOR REGULATOR MOTOR LH	Not Damaged	327.80 FL	*- FL
8	1		*FRONT DOOR INNER LOCK LH	Broken	328.90 FL	*328.90 FL
9	1		*FRONT DOOR LOCK STRIKER LH	Not Damaged	86.50 FL	*- FL
10	2		*FRONT DOOR HINGE LH	Not Damaged	164.00 FL	*- FL
11	1		*FRONT DOOR CHECKER ARM LH	Not Damaged	102.80 FL	*- FL
12	1		*FRONT DOOR TRIMBOARD LH	Not Damaged	496.90 FL	*- FL
13	1		*FRONT DOOR FRAME RUBBER LH	Torn	106.90 FL	*106.90 FL
14	1		*SIDE MIRROR ASSY LH	Not Damaged	658.30 FL	*- FL
15	1		*SIDE SKIRT LH	Dented	508.60 FL	*508.60 FL
16	1		*SIDE SKIRT FRAME RUBBER LH	Cut	154.80 FL	*154.80 FL
17	1		*REAR DOOR LH	Dented	2,023.60 FL	*2,023.60 FL
18	1		*REAR DOOR OUTER HANDLE LH	Not Damaged	189.30 FL	*- FL
19	1		*REAR DOOR WEATHERSTRIP LH	Not Damaged	284.60 FL	*- FL
20	1		*REAR DOOR REGULATOR LH	Not Damaged	684.60 FL	*- FL
21	1		*REAR DOOR REGULATOR MOTOR LH	Not Damaged	327.80 FL	*- FL
22	1		*REAR DOOR INNER LOCK LH	Not Damaged	328.90 FL	*- FL
23	1		*REAR DOOR LOCK STRIKER LH	Not Damaged	86.50 FL	*- FL
24	2		*REAR DOOR HINGE LH	Not Damaged	164.00 FL	*- FL
25	1		*REAR DOOR CHECKER ARM LH	Not Damaged	102.80 FL	*- FL
26	1		*REAR DOOR TRIMBOARD LH	Not Damaged	496.80 FL	*- FL
27	1		*REAR DOOR FRAME RUBBER LH	Not Damaged	106.90 FL	*- FL
28	1		*DOOR CENTRE PILLAR LH	Dented	872.00 FL	*872.00 FL
29	1		*FRONT SHOCK ABSORBER LH	Not Damaged	729.00 FL	*- FL
30	1		*FRONT LOWER ARM LH	Not Damaged	425.00 FL	*- FL
31	1		*FRONT KNUCKLE ARM LH	Dented	985.63 FL	*625.00 FL
32	1		*FRONT KNUCKLE ARM BEARING LH	Jammed	482.00 FL	*150.00 FL
33	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
34	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
35	1		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*40.00 FS
37	1		*FRONT DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
38	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*SIDE SKIRT CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*40.00 FS
41	1		*REAR DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
42	1		*REAR DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
43	1		*FRONT ALLOY RIM LH	Not Damaged	750.00 FS	*- FS
44	1		*FRONT TYRE LH	Not Damaged	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,830.66	7,962.50
- List Item Discount on L Items 10.00/10.00% (\$)	1,570.07	776.25
Total Parts (\$)	16,260.59	7,186.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT DOOR COMPONENT	New	150.00	60.00
2	R&R REAR DOOR COMPONENT	New	150.00	60.00
3	R&R FRONT UNDER CARRIAGE	New	150.00	80.00
4	R&R FRONT TYRE AND BALANCING	New	80.00	0.00
5	WHEEL ALIGNMENT	New	120.00	60.00
6	RUST PROOFING	New	100.00	60.00
7	UPHOLSTERY	New	200.00	0.00
8	CHECK WIRING	New	100.00	60.00
9	DIAGNOSTIC AND RESET FAULT CODE	New	300.00	80.00
10	PANEL BEATING	New	1,800.00	1,000.00
11	SPRAY PAINT	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			4,950.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >