

Lke

CHINA

COMFORTBELORO ENGINEERING PTE LTD

Date: 17.07.2020

REPAIR ESTIMATE

Time: 14:05:21

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305411493
 REGN NO : SHA2834Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 12.07.2018
 DATE/TIME IN : 16.07.2020 17:30
 ACCIDENT DATE : 16.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	de ✓
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nr ✓
0003	04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-Rear ^{Bumper (Black)}	1 L	451.25	20.00	361.00	cur ✓
0004	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUMPER ^{Lower Ctr}	1 L	155.00	20.00	124.00	Rx ✓
0005	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	2.00-	180.00	nr ✓
0006	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	0.20	50.00	nr ✓
0007	04-01-0104-2532-G	IONIQVC BRACKET ASSY-RR Bumper ^{Rh}	1 L	55.80	20.00	44.64	Rh ✓

SUB-TOTAL : 1,144.76

JOB NATURE

0000	23-01	TOWING FEE	60.00	✓
0001	L	PANEL BEATING	350.00	320
0002	23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200.
0003	20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
 W.P.

17/7/2020 3pm

P/P Resurvey before paint
 2 days
 Tanpin @ Pukubun

Date/Time: 17.07.2020 11:32

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4019709

JC NO.: 305411493

COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO: SHA2834Y MAKE: HYUNDAI MODEL: IONIQ(G2) YR OF MANU: 12.07.2018 CHASSIS CODE: KMHC851CVJU103514	MILEAGE FUEL DATE/TIME IN: 16.07.2020 17:30 TARGET DATE COMPLETION DATE/TIME:
---	---	---


CHINA

Accident Date: 16.07.2020
NATURE: 3P 16.07.2020

JOB DESCRIPTION

LABOR CODE
23-01

DESCRIPTION
TOWING FEE — \$60



RECEIVED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

SHA2834Y

LKE

Taufik

Exit Pass

Vehicle No:

SHA2834Y

Name of Service Advisor

Date