



**TRANS EUROKARS PTE LTD**



**FINALISED COST OF REPAIRS**

<b>CHINA TAIPING INSURANCE P/L</b>		<b>NAME : Ms Ng Poh Heng</b>		<b>WIP : 30994</b>	
3 ANSON ROAD		<b>ADDRESS : No.40 Jalan Limau Manis</b>		<b>EXCESS :</b>	
#16-00 SPRINGLEAF TOWER		Singapore 468368		<b>DATE: 14-Jul-20</b>	
SINGAPORE 079909		<b>TEL : 96213142</b>			
<b>ATTN. : MOTOR CLAIMS</b>					
<b>FAX :</b>					
<b>VEH NO :</b>	<b>SBT6138T</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	Ronald 63957875
<b>CHASSIS NO :</b>	JM6BM42A8G0321012	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	<b>THIRD PARTY CLAIM</b>
<b>MODEL :</b>	MAZDA 3	<b>DATE REG.:</b>	19-Oct-15	<b>POLICY NO. :</b>	

**NATURE OF WORKS**

**Parts Description**

NO	QTY		REVISED	PRICES
1	FRONT BUMPER	1	MBHR3-50-031BBB	\$ 1,083.30 \$ 1,083.30
2	RETAINER RHS	1	MBHN1-50-0T1F	\$ 19.70 \$ 19.70
3	BRACKET RHS, FRONT BUMPER	1	MBHN1-50-152	\$ 15.90 \$ 15.90
4	CHROME COVER RHS, FOG LAMP	1	MBJE1-50-C12	\$ 111.50
5	COVER RHS, FOG LAMP	1	MBJE1-50-C11A	\$ 48.80
6	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.80
7	CLIP, FRONT BUMPER	12	MC274-50-133	\$ 44.40 \$ 44.40
8	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 6.00 \$ 6.00
9	FRONT GRILLE	1	MBJE1-50-712B	\$ 610.70
10	CHROME RHS	1	MBHN1-50-7J1A	\$ 185.60
11	BRACKET RHS, FRONT GRILLE	1	MBHN1-50-153	\$ 15.90
12	RIVET, FRONT GRILLE	2	MEA01-50-037	\$ 16.00 \$ 16.00
13	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A	\$ 5.80
14	GROMMET, FRONT GRILLE	2	MKD45-50-ES1	\$ 5.80 \$ 5.80
15	RIVET, GRILLE TOP	6	MS51S-51-833	\$ 24.00 \$ 24.00
16	FASTENER, GRILLE	8	MGD7A-50-EA1	\$ 25.60 \$ 25.60
17	RIVET, GRILLE	4	MTK21-50-355	\$ 36.80 \$ 36.80
18	FRONT FENDER RHS	1	MB45A-52-111B	\$ 350.60
19	STAY RHS, FRONT FENDER	1	MB4ZA-52-1R0A	\$ 37.40
20	MUDGUARD RHS	1	MB45A-56-130H	\$ 101.90
21	FASTENER, MUDGUARD	15	MB45A-56-146A	\$ 45.00
22	HEADLAMP LHS	1	MBHT6-51-041A	\$ 2,357.30 \$ 2,357.30
23	CLIP, HEADLAMP	2	MFB01-50-133C	\$ 8.00 \$ 8.00
24	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.50 \$ 3.50
25	LAMP RHS, SIDE TURN	1	MB45A-51-350A	\$ 165.20
26	FOGLAMP RHS	1	MTK21-51-680A	\$ 369.00
27	BRACKET RHS, FOG LAMP	1	MBHR1-51-684A	\$ 18.20
28	NOZZLE RHS, HEADLAMP WASHER	1	MBHT4-51-8G1 64	\$ 89.40
29	ACTUATOR RHS	1	MBHT4-51-82X	\$ 254.60
30	CLAMP, ACTUATOR	1	MTK33-51-829	\$ 17.30

31	PIPE NOZZLE, ACTUATOR	1	MBHT4-51-4J0		\$ 128.90
32	WASHER TANK	1	MGHP9-67-481A	\$ 97.50	\$ 97.50
33	CAP, WASHER TANK	1	MGHP9-67-483	\$ 17.10	\$ 17.10
				<b>TOTAL PARTS</b>	\$ 3,760.90 \$ 6,322.50
				<b>TOTAL PARTS COST</b>	\$ 3,760.90 \$ 6,322.50

**Labour Description**

1	MZ-BR-FRONT7	TO REPLAC EFRONT BUMPER. TO REPAIR FRONT FENDER RH.		\$ 990.00	\$ 1,650.00
2	MZ-SP-SFRTO7	TO RESPRAY FRONT BUMPER AND FRONT FENDER.		\$ 945.00	\$ 1,575.00
3	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 120.00	\$ 250.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.		\$ 20.00	\$ 100.00
			<b>TOTAL LABOUR</b>	\$ 2,255.00	\$ 4,175.00
			<b>TOTAL PARTS</b>	\$ 3,760.90	\$ 6,322.50
			<b>TOTAL</b>	\$ 6,015.90	\$ 10,497.50
			<b>LESS EXCESS</b>	\$ -	\$ -
			<b>TOTAL AFTER EXCESS</b>	\$ 6,015.90	
			<b>GST 7%</b>	\$ 421.11	\$ -
			<b>GRAND TOTAL</b>	\$ 6,437.01	\$ -

**REMARKS:**

**4 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)**