

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42011

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0503/2020/NS
Date	:	20-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Mario Traeber
Address	:	11 Thomson Lane #15-08 Singapore 297727
Telephone	:	+(HP) 81891985
Type of Claim	:	Own Damage Claim
Policy No.	:	
Vehicle No	:	SKG 5268 U
Model Code	:	Audi Q5 2.0 TFSI qu
Model / Year	:	May-18
Engine No	:	DAX 032618
Chassis No	:	WAUZZZF6J2136117
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	17-Jul-20
Place of Accident	:	Balestier Road Combat Durian

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKG 5268 U

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front bumper wire harness for front parking aid.	S/N \$ 280.00 ✓	
2	To remove and transfer headlight control units, power modules, electrical fans and connectors.	S/N \$ 900.00 X	
3	To dismantle front bumper, inspect front lock carrier for damages. Renew charge air cooler, front bumper assy and both front headlights. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00 ✓ \$500	SSD Bumpers
4	✓ To respray front bumper, lower spoiler and wheel arch trims.	\$ 1300 ✓ 2,200.00	350 Spoiler
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	400. trim x 0.2
TOTAL LABOUR CHARGES		: \$ 4,772.00	<u>1300</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 5268 U

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Rehnd</i>	\$	2,595.00	✓
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$	267.00	✓
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>neu 2</i>	\$	222.00	✓
4	FRONT BUMPER GRILLE - CENTRE <i>?</i>	\$	142.00	✓
5	FRONT SPOILER <i>?</i>	\$	754.00	✓
6	FRONT BUMPER UNDERRUN BAR <i>?</i>	\$	474.00	✓
7	FRONT BUMPER CLOSING ELEMENT <i>neu</i>	\$	171.00	✓
8	RADIATOR GRILLE <i>Cracked</i>	\$	3,490.00	✓
9	RADIATOR GRILLE STRIKER PLATE <i>?</i>	\$	241.00	?
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>neu</i>	\$	574.00	✓
11	FRONT BUMPER END CAP - LH <i>neu</i>	\$	91.00	✓
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>wt</i>	\$	574.00	✓
13	FRONT BUMPER END CAP - RH <i>neu</i>	\$	91.00	✓
14	LOCKING CLIP <i>?</i>	\$	15.00	?
15	FRONT PARKING AID SENSOR - INNER <i>neu</i>		TBC	?
16	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$	285.00	?
17	FRONT BUMPER CARRIER <i>?</i>	\$	911.00	?
18	FRONT BUMPER SIGHT SHIELD <i>neu</i>	\$	127.00	✓
19	CAUTION SIGN STICKER <i>3 neu</i>	NEC \$	14.00	✓
20	AIRCON STICKER	NEC \$	20.00	✓
SUB TOTAL SPARE PARTS CHARGES			\$ 11,058.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 5268 U

S/N	Parts Description	Damage Parts & Prices		
		S/Nett	Remarks	
21	FRONT WHEEL COVER - LH / RH <i>None</i>	2 \$ 1,250.00	✓	
22	LED HEADLIGHT - LH / RH <i>None</i>	2 \$ 22,722.00	+	
23	HEADLIGHT MOUNTING - LH / RH <i>None</i>	2 \$ 234.00	+	
24	RADIATOR AIR GUIDE - RH <i>?</i>	\$ 58.00	?	
25	CHARGE AIR COOLER <i>None</i>	\$ 785.00	+	
26	PRESSURE PIPE SEAL	2 \$ 88.00	+	
27	FRONT NO PLATE <i>Dented</i>	S/N \$ 40.00	✓	
28	SUNDRIES <i>?</i>	\$ 200.00	?	
TOTAL SPARE PARTS CHARGES		:	\$36,435.00	
TOTAL LABOUR CHARGES		:	\$ 4,772.00	
GRAND TOTAL		:	\$41,207.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Admin
20/07/2017

All Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant