

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42011

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0503/2020/NS
Date : 20-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Mario Traeber
Address : 11 Thomson Lane
#15-08
Singapore 297727
Telephone : +(HP) 81891985
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SKG 5268 U**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : May-18
Engine No : DAX 032618
Chassis No : WAUZZZF6J2136117
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Jul-20
Place of Accident : Balestier Road Combat Durian

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKG 5268 U

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front bumper wire harness for front parking aid.	S/N \$	280.00	✓✓
2	To remove and transfer headlight control units, power modules, electrical fans and connectors.	S/N \$	900.00	X✓500
3	To dismantle front bumper, inspect front lock carrier for damages. Renew charge air cooler, front bumper assy and both front headlights. Re-organise front crash management components. Reinstall all parts removed.	\$	1,200.00	500 ✓
			1300 ✓	
4	To respray front bumper, lower spoiler and wheel arch trims.	\$	2,200.00	550 Bumper 350 Spoiler
5	To carry out diagnostic check.	S/N \$	192.00	400. trim x 02
TOTAL LABOUR CHARGES		:	\$ 4,772.00	1300

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 5268 U

Damage Parts & Prices

S/N	Parts Description		S/Nett	Remarks
1	FRONT BUMPER <i>Dehnd</i>	\$	2,595.00	✓ 2075.60
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$	267.00	+
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>neu</i> 2	\$	222.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>Dehnd</i>	\$	142.00	✓ 113.60
5	FRONT SPOILER <i>Dehnd</i>	\$	754.00	✓ 603.20
6	FRONT BUMPER UNDERRUN BAR <i>Dehnd</i>	\$	474.00	✓ 379.20
7	FRONT BUMPER CLOSING ELEMENT <i>neu</i>	\$	171.00	+
8	RADIATOR GRILLE <i>Dehnd</i>	\$	3,490.00	✓ 2792
9	RADIATOR GRILLE STRIKER PLATE ? NN	\$	241.00	? X
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>neu</i>	\$	574.00	+
11	FRONT BUMPER END CAP - LH <i>neu</i>	\$	91.00	+
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>ut</i>	\$	574.00	✓ 458.80
13	FRONT BUMPER END CAP - RH <i>neu</i>	\$	91.00	+
14	LOCKING CLIP ? NN 4	\$	15.00	? X
15	FRONT PARKING AID SENSOR - INNER <i>neu</i> 2		TBC	? X
16	FRONT BUMPER FOAM FILLER PIECE <i>Dehnd</i>	\$	285.00	✓ 228
17	FRONT BUMPER CARRIER <i>Dehnd</i>	\$	911.00	✓ 728.40
18	FRONT BUMPER SIGHT SHIELD <i>neu</i>	\$	127.00	+
19	CAUTION SIGN STICKER } <i>neu</i> NEC	\$	14.00	+
20	AIRCON STICKER } <i>neu</i> NEC	\$	20.00	+
SUB TOTAL SPARE PARTS CHARGES			: \$ 11,058.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 5268 U

S/N	Parts Description			Damage Parts & Prices	
				S/Nett	Remarks
21	FRONT WHEEL COVER - LH / RH <i>Alu</i>	2	\$	1,250.00	✓ 1000
22	LED HEADLIGHT - LH / RH <i>Alu</i>	2	\$	22,722.00	+
<i>RH</i> 23	HEADLIGHT MOUNTING - LH / RH <i>Not a RH cashed</i>	2	\$	234.00	<i>117</i> 93.60
24	RADIATOR AIR GUIDE - RH <i>Reband.</i>		\$	58.00	✓ 45.76
25	CHARGE AIR COOLER <i>Alu</i>		\$	785.00	+
26	PRESSURE PIPE SEAL	2	\$	88.00	+
27	FRONT NO PLATE <i>Dented</i>	S/N	\$	40.00	✓ 40
28	SUNDRIES <i>✓ Nec</i>		\$	200.00	? 70.40
TOTAL SPARE PARTS CHARGES			:	\$36,435.00	
TOTAL LABOUR CHARGES			:	\$ 4,772.00	
GRAND TOTAL			:	\$41,207.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

47,478.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan L
Surveyed Date : 20/07/20
Authorised Date :
Excess Cost :
Liability :
Remarks : All Authorised, 03 Days + 4 Days
HRS.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0503/2020/NS 23-Jul-20 Glory Tan 1 of 1 SKG 5268 U Audi Q5 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>checked</i>	\$ 1,384.00	✓ 1107.20
2	Radiator coolant <i>new</i>	\$ 91.00	✓ 72.32
3	Charged air cooler <i>new</i>	\$ 785.00	x 122.40
4	Wheel spoiler rhs <i>checked</i>	\$ 153.00	✓ 12.56
5	Temperature sensor bracket <i>checked</i>	\$ 16.00	✓ 32.88
6	Radiator air guide centre <i>checked</i>	\$ 42.00	
Labours			
1	To remove and reinstall aircon condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	s/n \$ 1,400.00	✓ ✓
2	To renew front lock carrier and align to position.	\$ 2,400.00	1250 ✓
TOTAL		\$ 6,271.00	

For Premium Automobiles Pte Ltd

 Authorised Signature