

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0503/2020/NS

Date

23-Jul-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKG 5268 U

Model No

Audi Q5 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>changed</i>	\$ 1,384.00	✓
2	Radiator coolant <i>new</i>	\$ 91.00	✓
3	Charged air cooler <i>new</i>	\$ 785.00	✓
4	Wheel spoiler rhs <i>changed.</i>	\$ 153.00	✓
5	Temperature sensor bracket <i>changed.</i>	\$ 16.00	✓
6	Radiator air guide centre <i>changed.</i>	\$ 42.00	✓
Labours			
1	To remove and reinstall aircon condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	s/n \$ 1,400.00	✓
2	To renew front lock carrier and align to position.	\$ 2,400.00	1250
TOTAL		\$ 6,271.00	

For Premium Automobiles Pte Ltd

Authorised Signature