



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Repair Estimates

YP 5229 U

Finalised

Parts (a) Cost / List Price Items	\$ 1095.10	1,095.10
Plus/Less <u>10% XS</u>	\$ 273.78	109.51
Total of Cost / List	\$ 821.33	985.59
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items		
Total Parts Cost		
Labour	\$ 140	600.00
Total	\$ 961.33	1,585.59

Not Authorized

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : CKK
Survey conducted on : 29/7/20 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 01 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : Sc Date: 29/7/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Car Parts

Vehicle No. :

Year & Model :

Chassis No. :

YP 5229 U

mitsubishi canter

FEB21EA20786

Submit By :

Year Manufacture :

Engine No. :

Carmen Lim

2016

Cost / List

No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Air cleaner box <i>CM</i>	1	\$1,095.10		☒
2					
3	<i>258</i>				
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

3: If any of the quoted parts are recommended to be repaired, then an additional labour charge
be charged accordingly under supplementary.



Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

146