

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CC6/CT/20007454/ues3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SVV 663C

at Workshop m/s

LP.

of

Insured:

SKB7675R

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 26800

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

off \$ 12322

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SVV663C

Yr Regn:

1110

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Hyundai Accent c.c 1591

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

90508

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHDU41BRMAU965247

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Ni / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/552218

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/7/20

D.O.I.

20/7/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

New h.A

Cor 10-01-2025 LTA \$ 14478

28/7/20 4/5 \$ 12.000 Confirmed with Alar.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: **SSV663C**

QTY	PARTICULAR
1 PCS	BOOTLID 907.60
1 PCS	BOOTLID REAR LOGO 32.50
1 PCS	BOOTLID 'AVANTE' EMBLEM 32.00
1 PCS	BOOTLID LOCK STRIKER
1 PCS	BOOTLID WEATHERSTRIP 165.30
1 PCS	BOOTLID INNER LOCK 183.60
2 PCS	BOOTLID REFLECTORS @ \$450.00 189.60 x 2 = 379.20
1 PCS	BOOTLID INNER TRIM
1 SET	BOOTLID INNER TRIM CLIPS
2 PCS	BOOTLID hinge
1 SET	BOOTLID REVERSE CAMERA
1 PCS	REAR BUMPER 486.90
1 PCS	REAR BUMPER CENTRE GARNISH
2 PCS	REAR BUMPER LAMPS @ \$300.00
2 PCS	REAR BUMPER SIDE RETAINERS @ \$52.00 45 x 2 = 90
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER LOWER TRAY
1 PCS	REAR BUMPER REINFORCEMENT 354.00
5 PCS	REAR BUMPER REINFORCEMENT TOP & BOTTOM BRACKETS @ \$18.00
2 PCS	REAR BUMPER REINFORCEMENT STAYS @ \$95.00
1 PCS	REAR BUMPER INNER LOCK SENSOR
1 SET	REAR BUMPER LICENCE LAMP
1 PCS	REAR END PANEL 637.90
1 PCS	REAR END PANEL TOP GARNISH 162.00
2 PCS	TAILLAMPS @ \$505.00 295.20 x 2 = 590.40
2 PCS	TAILLAMP HOUSING PANELS @ \$195.00
1 PCS	REAR FLOOR PANEL 480.10
1 PCS	REAR FLOOR PANEL TOP BOARD 316.00
2 PCS	REAR FENDERS @ \$1768.00
2 PCS	REAR FENDER INNER TRIM BOARDS @ \$255.00
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTAINS @ \$28.00
1 PCS	REAR EXHAUST HEAT SHIELD
1 PCS	BONNET
1 PCS	BONNET LOCK 145.50
2 PCS	BONNET HINGES @ \$85.00
1 PCS	BONNET INSULATOR
1 SET	BONNET INSULATOR CLIPS
1 PCS	FRONT BUMPER 480.60
2 PCS	FRONT BUMPER SIDE RETAINERS @ \$45.00
1 PCS	FRONT BUMPER CENTRE GARNISH 105.20
1 SET	FRONT BUMPER CLIPS
1 PCS	FRONT BUMPER REINFORCEMENT 366.80
1 PCS	FRONT BUMPER SPONGE 145.80
1 PCS	FRONT GRILLE 382.30
2 PCS	HEADLAMPS @ \$1500.00 681.60 x 2 = 1363.20

not Authorized
hike
20/7/20
4/5 @ 12.000/ 12 days

Bdy	\$2,400.00	---
ner	\$199.00	---
ner	\$85.00	---
11	\$85.00	X
twi	\$219.00	---
best	\$155.00	---
cna	\$900.00	---
ac/Toin	\$245.00	---
ner	\$50.00	---
11	\$330.00	X
11	\$650.00	X
7-5	\$1,150.00	---
NS	\$499.00	X
NS	\$600.00	X
best	\$104.00	---
ner	\$50.00	---
NS	\$495.00	X
cna	\$399.00	---
twi	\$90.00	---
best	\$190.00	---
NS	\$225.00	X
11	\$102.00	X
Bdy	\$665.00	---
twi	\$188.00	---
cna	\$1,010.00	---
R	\$390.00	X
crumpled/suc	\$1,128.00	---
worped	\$433.00	---
R	\$3,536.00	X
n/s To in	\$510.00	X
n	\$993.00	X
11	\$56.00	X
11	\$159.00	X
11	\$1,999.00	X
twi	\$195.00	---
11	\$170.00	X
11	\$221.00	X
11	\$50.00	X
no/oe	\$966.00	---
best	\$90.00	---
twi	\$185.00	---
ner	\$50.00	---
best	\$755.00	---
To in	\$199.00	---
cna	\$1,082.00	---
holder cna	\$3,000.00	---

(202)

1 PCS FRONT SUPPORT PANEL 978
 1 PCS FRONT SUPPORT PANEL GARNISH
 1 PCS FRONT LICENCE PLATE HOLDER
 2 PCS FRONT BUMPER FOG LAMPS @\$330.00
 1 PCS FRONT BUMPER LOWER SKIRTING
 2 PCS HEADLAMP LOWER BRACKETS @\$45.00
 1 PCS AIR CON CONDENSER
 2 PCS AIR CON CONDENSER SIDE GARNISHS @\$85.00 950
 1 PCS RADIATOR 895.00
 1 PCS RADIATOR FAN ASSY 645
 2 PCS FRONT FENDERS @\$966.00
 1 PCS AIR DUCT
 1 PCS AIR CLEANER BOX ASSY
 1 PCS FRONT BUMPER LOWER RETAINER

S.NETT
 1 SET REAR BUMPER REVERSE SENSOR
 1 PCS REAR END panel SEALANT
 1 PCS REAR WINDSCREEN SEALANT
 1 PCS REAR LICENCE PLATE W/HOLDER
 1 SET REAR FLOOR PANEL INSULATOR
 1 PCS FRONT LICENCE PLATE W/HOLDER
 1 BOT RADIATOR COOLANT

LABOUR CHARGES:

TO CHECK WIRING
 TO DISMANTLE & REPLACING REVERSE SENSOR
 TO TRANSFER BOOTLID MECHANISM
 TO DISMANTLE & REFIX REAR EXHAUST
 TO DISMANTLE & REFIX PETROL TANK
 TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY
 TO REFILL AIR CON GAS
 TO SPRAY RUST PROOFING
 TO MOUNT VEHICLE ON CAR O-LINER
 LABOUR FOR PANEL BEATING & REPLACING PARTS
 TO PUTTY & SPRAY PAINTING

Tw/cne \$1,455.00 ✓
 NS \$139.00 X
 NX \$136.00 X
 NX \$660.00 X
 NX \$385.00 X
 NS \$90.00 X
 Bent/pun \$1,132.00 ✓
 Torn \$170.00 ✓
 Bent/pun \$1,575.00 ✓
 Cra/ym \$568.00 ✓
 n \$1,932.00 X
 n \$148.00 X
 n \$388.00 X
 n \$118.00 X
 \$36,148.00

shodd \$380.00 200
 ne \$50.00 ✓
 n \$50.00 X
 Cne \$50.00 40
 ne \$280.00 120
 Cne \$50.00 40
 ne \$50.00 30

\$80.00 30
 \$80.00 50
 \$100.00 60
 n \$100.00 X
 \$100.00 60
 \$120.00 80
 \$150.00 100
 \$150.00 100
 n \$380.00 X
 \$2,800.00 2000
 \$2,500.00 1800
 TOTAL \$43,618.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-12867
 201
 1-1029360
 541-480.00
 1-4280.00
 15053.6
 11421