



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address

Subway Electronics Components

101 Kitchener Road
#02-11 Jalan Besar Plaza
Singapore 208511
Attn: Ms Eleen

Contact No Work: 62923229

Owner Name & Vehicle Info

Reg No/Reg Date GBH1677A*M / 28/02/2018
Date In/Mileage / 0
Chassis No *WDF4156052U223036
Engine No 607951A0223036
Make/Model CITAN 109CDI VAN

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00061	Cash	25/07/2020/ 11:15	QUK	282 / Kevin Leong	24054			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E	PNT88000	TO RENEW REAR BOTH TAILGATE, REAR BUMPER & AFFECTED AREA TO REPAIR ON REAR END PANEL						1280 1600.00
E	PNT98000	PAINT WORK ON REAR BOTH TAILGATE, REAR BUMPER & END PANEL						1000 1400.00
E	PNT88000	TO REMOVE & INSTALL REAR PARKING ASSIST						80 160.00
E	PNT88000	TO REPLACE BOTH REAR TAILGATE GLASS						480.00
M	SUNDRY	TO APPLY BOTH REAR TAILGATE GLASS SEALANT						160.00
E	PNT88000	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR						120.00
M	SUNDRY	TO APPLY SEALANT FOR AFFECTED AREA						60 100.00
M	SUNDRY	PERFORM RUST PREVENTION						100.00
M	SUNDRY	TO SUPPLY SPEED LIMIT STICKER						20.00
M	SUNDRY	TO SUPPLY PAX STICKER						20.00
M	SUNDRY	TO SUPPLY C & C LOGO						40.00
A	54900099	CHECK CHASSIS & ELECTRICAL SYSTEM						60 80.00
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						200.00
M	SUNDRY	TO SUPPLY REAR NUMBER PLATE WITH FRAME <i>SCA</i>						50.00
M	SUNDRY	SUNDRIES						30 50.00
M	SUNDRY							1473.25

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4558 Fax: (65) 6567 5258

**DPS****Diplomat Parts Pte. Ltd.**Company Reg No. 196400304H
GST Reg No. MR-8500111-X**ESTIMATE**

Invoice Name & Address		Owner Name & Vehicle Info	
Subway Electronics Components		Reg No/Reg Date	GBH1677A*M / 28/02/2018
101 Kitchener Road		Date In/Mileage	/ 0
#02-11 Jalan Besar Plaza		Chassis No	*WDF4156052U223036
Singapore 208511		Engine No	607951A0223036
Attn: Ms Eleen		Make/Model	CITAN 109CDI VAN
Contact No	Work: 62923229		

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00061	Cash	25/07/2020/ 11:15	QUK	282 / Kevin Leong	24054			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REAR DOOR LEFT (A4157401400) <i>bt</i>							✓ 1372.95
M	SUNDRY							
M	REAR DOOR RIGHT (A4157401500) <i>bt</i>							184.15
M	SUNDRY							
M	TRIM (A4157470300) ? <i>xsu</i>							235.45
M	SUNDRY							
M	SEALING REAR-END DOOR (A4157410180) ? <i>xsu</i>							187.60
M	SUNDRY							
M	REAR WINDOW LEFT (A4156780910) <i>x xsu</i>							113.72
M	SUNDRY							
M	REAR WINDOW RIGHT (A4156781110) <i>x xsu</i>							2.61
M	SUNDRY							
M	RETAINING GROMMET (A2019972281) <i>rec</i>							✓ 52.34
M	SUNDRY							
M	MODEL PLATE LEFT (A4158170200) <i>rec</i>							✓ 56.77
M	SUNDRY							
M	MODEL PLATE RIGHT (A4158170514) <i>rec</i>							3.52 ✓ 7.04
M	SUNDRY							
M	SPREADER NUT (A0009982685) <i>rec</i>							✓ 1124.21
M	SUNDRY							
M	TS TRIM BUMPER (A4158800140) <i>de</i>							303.43
M	SUNDRY							
M	BRACKET BASIC CARRIER (A4158840015) ? <i>xsu</i>							195.68
M	SUNDRY							
M	RS BRACKET BUMPER (A4158850014) ? <i>xsu</i>							✓ 522.38
M	SUNDRY							
M	TS COVER BUMPER AREA (A4158800024) <i>de</i>							149.56
M	SUNDRY							
M	ATTACHING PARTS REAR BUMPER (A4159901499) ? <i>xsu</i>							484.37
M	SUNDRY							
M	ELECTRICAL WIRING HARNESS (A4155403205) ? <i>xsu</i>							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *Rasul - Hp 90010068*

SURVEYOR SIGNATURE: *[Signature]*

DATE: *07/08/2020 @ 1030*

REMARKS: *9 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *Rasul - Hp 90010068*SURVEYOR SIGNATURE: *R*DATE: *07/08/2020 @ 1030*REMARKS: *9 days**Resy before paint*

Confirm & accepted by

7% GST on **Nett** **11,045.51**
 11045.51 **773.19**

Authorized signatory and company stamp

Total Payable 11,818.70

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.