



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT20002185	Page	1
Registration No	: SLA8539M	Date	: 18. Jul 2020	Customer No.	: WZI007
Chassis No	: MRHRU1830FP000834	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15Z71001525
Model	: HRV LX-SIN CVT YM 2015	Date Time	: 18. Jul 2020 11:00:30 AM	Surveyor Name	:
Owner's Name	: KHO SOON IMM	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 17/7/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KHO SOON IMM OWNER INSURER: LIBERTY INSURANCE ACC DATE: 17/07/2020 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL TP VEH: SHB4452Y						
68100-T8P-U10ZZ	TAILGATE COMP	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE	1	101.30	25	75.97	5.32	81.29
74800-T7A-J01	LOCK ASSYTAILGATE	1	86.20	25	64.65	4.53	69.18
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER	1	108.00	25	81.00	5.67	86.67
75722-T7W-A01	EMBLEMRR.	1	14.60	25	10.95	0.77	11.72
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	15.90	25	11.92	0.83	12.75
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE	1	189.80	25	142.35	9.96	152.31
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
34150-T7A-J01	LIGHT ASSY,R.LID	1	276.90	25	207.67	14.54	222.21
34155-T7A-J01	LIGHT ASSYL.LID	1	276.90	25	207.67	14.54	222.21
33502-T7A-J01	LAMP UNITR.	1	482.40	25	361.80	25.33	387.13
33552-T7A-J01	LAMP UNITL.	1	482.40	25	361.80	25.33	387.13
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER	1	97.60	25	73.20	5.12	78.32
71501-T8N-T50	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	170.80	25	128.10	8.97	137.07
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	170.80	25	128.10	8.97	137.07
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER	1	91.20	25	68.40	4.79	73.19
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER	1	91.20	25	68.40	4.79	73.19

Printed on 18/7/2020 12:02:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT20002185	Page	2
Registration No	: SLA8539M	Date	: 18. Jul 2020	Customer No.	: WZI007
Chassis No	: MRHRU1830FP000834	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15Z71001525
Model	: HRV LX-SIN CVT YM 2015	Date Time	: 18. Jul 2020 11:00:30 AM	Surveyor Name	:
Owner's Name	: KHO SOON IMM	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 17/7/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
66100-T8N-T00ZZ	PANEL COMPRR.	1	450.10	25	337.57	23.63	361.20
84640-T8N-T01ZA	LINING ASSYRR.PANEL	1	66.60	25	49.95	3.50	53.45
04655-T7Y-T00ZZ	PANEL SETRR.FLOOR	1	553.00	25	414.75	29.03	443.78
65513-T7J-H00ZZ	STIFFENERRR.JACK UP	1	42.60	25	31.95	2.24	34.19
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	5.00	25	3.75	0.26	4.01
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
				Sum Item	4420.41	309.45	4,729.86

BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	150.00		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT END PANEL	1	150.00		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	150.00		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50

Printed on 18/7/2020 12:02:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT20002185	Page	3
Registration No	: SLA8539M	Date	: 18. Jul 2020	Customer No.	: WZI007
Chassis No	: MRHRU1830FP000834	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15Z71001525
Model	: HRV LX-SIN CVT YM 2015	Date Time	: 18. Jul 2020 11:00:30 AM	Surveyor Name	:
Owner's Name	: KHO SOON IMM	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 17/7/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00		560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	350.00		350.00	24.50	374.50
BKRP02B	CUT & RENEW RR FLOOR PANEL,END PANEL & DAMAGE PART	1	6500.00		6500.00	455.00	6955.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4160.00		4160.00	291.20	4451.20
BOBC	BODY UNDERSIDE COATING (N)	1	450.00		450.00	31.50	481.50
Sum Labor					15540.00	1,087.80	16,627.80

Survey By	_____				
Date & Time	_____	Total Amount	19,960.41	1,397.25	21,357.66
Excess	_____	Total (Inclusive of GST)	21,357.66		
Status	_____				
Signature	_____				

Printed on 18/7/2020 12:02:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.