



HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

Customer :	INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No. :	SQT20002185	Page	1
Registration No :	SLA8539M	Date	: 18. Jul 2020	Customer No.	: WZI007
Chassis No :	MRHRU1830FP000834	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15Z71001525
Model :	HRV LX-SIN CVT YM 2015	Date Time	: 18. Jul 2020 11:00:30 AM	Surveyor Name	:
Owner's Name :	KHO SOON IMM	Survey Date	:	Authorisation Date	:
Ins Policy No. :					
Date of Accident :	17/7/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KHO SOON IMM OWNER INSURER: LIBERTY INSURANCE ACC DATE: 17/07/2020 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL TP VEH: SHB4452Y						
68100-T8P-U10ZZ	TAILGATE COMP <i>bt</i>	1	855.70	25	556.28	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE <i>new</i>	1	101.30	25	65.84	5.32	81.29
74800-T7A-J01	LOCK ASSYTAILGATE <i>? XSVL</i>	1	86.20	25	64.65	4.53	69.18
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>? XSVL</i>	1	108.00	25	81.00	5.67	86.67
75722-T7W-A01	EMBLEMRR. <i>new</i>	1	14.60	25	9.49	0.77	11.72
75725-T8N-T00	EMBLEM,RR, I-VTEC <i>new</i>	1	15.90	25	10.33	0.83	12.75
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE <i>XSVL</i>	1	189.80	25	142.35	9.96	152.31
75701-T5A-000	EMBLEMH <i>new</i>	1	10.70	25	35.96	0.56	8.58
90301-ST0-003	NUTPUSH 3MM <i>new</i>	2	2.10	25	3.73	0.22	3.37
34150-T7A-J01	LIGHT ASSY,R.LID <i>? XSVL</i>	1	276.90	25	207.67	14.54	222.21
34155-T7A-J01	LIGHT ASSY,L.LID <i>? XSVL</i>	1	276.90	25	207.67	14.54	222.21
33502-T7A-J01	LAMP UNTR. <i>? XSVL</i>	1	482.40	25	361.80	25.33	387.13
33552-T7A-J01	LAMP UNTL. <i>? XSVL</i>	1	482.40	25	361.80	25.33	387.13
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER <i>? XSVL</i>	1	97.60	25	73.20	5.12	78.32
71501-T8N-T50	FACERR.BUMPER <i>de</i>	1	463.70	25	301.43	24.34	372.11
33505-T7A-J01	REFLECTOR ASSYR.RR. <i>? XSVL</i>	1	170.80	25	128.10	8.97	137.07
33555-T7A-J01	REFLECTOR ASSYL.RR. <i>? XSVL</i>	1	170.80	25	128.10	8.97	137.07
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER <i>repair X</i>	1	91.20	25	68.40	4.79	73.19
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER <i>repair X</i>	1	91.20	25	68.40	4.79	73.19

Printed on 18/7/2020 12:02:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Gen. Conv.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLA8539M

Chassis No : MRHRU1830FP000834

Model : HRV LX-SIN CVT YM 2015

Owner's Name : KHO SOON IMM

Ins Policy No. :

Date of Accident : 17/7/2020

Document No. : SQT20002185

Date : 18. Jul 2020

Customer No. : WZ1007

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L15Z71001525

Date | Time : 18. Jul 2020 11:00:30 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incd GST
71593-T7A-000	SPACER,R.RR.BUMPER SIDE <i>new</i>	1	17.30	25	11.24	12.97	13.88
71598-T7A-000	SPACER,L.RR.BUMPER SIDE <i>new</i>	1	17.30	25	11.24	12.97	13.88
91505-TM8-003	CLIP,BUMPER <i>new</i>	8	2.30	25	11.96	13.80	14.77
66100-T8N-T00ZZ	PANEL COMPRR. <i>bt</i>	1	450.10	25	302.58	337.57	361.20
84640-T8N-T01ZA	LINING ASSYRR.PANEL <i>de-</i>	1	66.60	25	48.29	49.95	53.45
04655-T7Y-T00ZZ	PANEL SETRR.FLOOR <i>bmc</i>	1	553.00	25	394.8	414.75	443.78
65513-T7J-H00ZZ	STIFFENERRR.JACK UP <i>new</i>	1	42.60	25	27.69	31.95	34.19
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>new X SUL</i>	1	320.00	25	235	320.00	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>new</i>	1	45.00			45.00	48.15
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>new</i>	1	19.30	25	12.54	14.47	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>new</i>	1	8.70	25	5.65	6.52	6.98
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>new</i>	1	19.30	25	12.54	14.47	15.48
76711-T6A-003	CAPPVOT <i>new</i>	1	5.00	25	3.25	3.75	4.01
91501-S70-003	FASTENER BW/SHIELD <i>new</i>	4	5.30	25	13.28	15.90	17.01
91502-S70-003	FASTENER B <i>new</i>	2	5.30	25	6.89	7.95	8.51
91536-SS0-J01	FASTENER AW/SHIELD <i>new</i>	2	3.80	25	4.94	5.70	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>new</i>	2	60.00			120.00	128.40
Sum Item					4420.41	309.45	4,729.86

BOSUN	SUNDRIES	1	100.00	50	50.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00	340	310.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	150.00	120	30.00	10.50	160.50
BOJSE	BODY JOINT SEALANT END PANEL	1	150.00	120	30.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	150.00	120	30.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	150 150	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	150 140	180.00	12.60	192.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	50 325	650.00	45.50	695.50

Printed on 18/7/2020 12:02:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711

Registration No : SLA8539M
 Chassis No : MRHRU1830FP000834
 Model : HRV LX-SIN CVT YM 2015
 Owner's Name : KHO SOON IMM
 Ins Policy No. :
 Date of Accident : 17/7/2020

Document No. : SQT20002185 Page 3
 Date : 18. Jul 2020
 Customer No. : WZ1007
 Svc Advisor : IVAN TEO BOON KIAT
 Engine No : L15Z71001525
 Date | Time : 18. Jul 2020 11:00:30 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	480	560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00	480	560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	325	650.00	45.50	695.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	350.00		350.00	24.50	374.50
BKRP02B	CUT & RENEW RR FLOOR PANEL, END PANEL & DAMAGE PART @650	1	6500.00	350	6500.00	455.00	6955.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P) @520	1	4160.00	2600	4160.00	291.20	4451.20
BOBC	BODY UNDERSIDE COATING (N)	1	450.00	300	450.00	31.50	481.50
Sum Labor					15540.00	1,087.80	16,627.80

Survey By RASUL - Hp 90010068

Date & Time 23/07/2020 @ 1130

Excess _____

Status _____

Signature [Signature]

12 days

Resy before paint

Total Amount 19,960.41 1,397.25 21,357.66
 Total (Inclusive of GST) 21,357.66

* Supplementary
GPIs refer to Service
Pre-Invoice.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 18/7/2020 12:02:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0079037 / INDIA
 Chassis No: MRHRU1830FP000834
 License No: SLA8539M
 Mileage: 74675
 Engine No: L15Z71001525

Document No: SVO20035621
 Printed By: IVANTEO
 Order Date: 23. July 2020
 Order Time: 11:55:30 AM
 Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KHO SOON IMM OWNER INSURER: LIBERTY INSURANCE ACC DATE: 17/07/2020 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL TP VEH: SHB4452Y LIMIT REPAIR \$11K SUPPLEMENTARY PART						
68100-T8P-U10ZZ	TAILGATE COMP	1	855.70	35	556.20	38.93	595.13
74440-T7A-003	WEATHERSTRIPTAILGATE	1	101.30	35	65.84	4.61	70.45
75722-T7W-A01	EMBLEMRR.	1	14.60	35	9.49	0.66	10.15
75725-T8N-T00	EMBLEM.RR. I-VTEC	1	15.90	35	10.33	0.72	11.05
75701-T5A-000	EMBLEMH	1	10.70	35	6.95	0.49	7.44
90301-ST0-003	NUTPUSH 3MM	2	2.10	35	2.73	0.19	2.92
71501-T8N-T50	FACERR.BUMPER	1	463.70	35	301.40	21.10	322.50
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	17.30	35	11.24	0.79	12.03
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	17.30	35	11.24	0.79	12.03
91505-TM8-003	CLIP,BUMPER	8	2.30	35	11.96	0.84	12.80
66100-T8N-T00ZZ	PANEL COMP RR.	1	450.10	35	292.56	20.48	313.04
84640-T8N-T01ZA	LINING ASSYRR.PANEL	1	66.60	35	43.29	3.03	46.32
04655-T7Y-T00ZZ	PANEL SETRR.FLOOR	1	553.00	35	359.45	25.16	384.61
65513-T7J-H00ZZ	STIFFENERRR.JACK UP	1	42.60	35	27.69	1.94	29.63
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
73226-SZW-000	DAMPERSTD 5X5	1	8.70	35	5.65	0.40	6.05
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
76711-T6A-003	CAPPIVOT	1	5.00	35	3.25	0.23	3.48
91501-S70-003	FASTENER BW/SHIELD	4	5.30	35	13.78	0.96	14.74
91502-S70-003	FASTENER B	2	5.30	35	6.89	0.48	7.37
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	35	4.94	0.35	5.29
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
90661-SC7-003	GROMMET SCREW nec / (S)	2	2.40	35	3.12	0.22	3.34
91513-T6A-003	CLIPTAILGATE SPOILER nec / (S)	9	2.50	35	14.62	1.02	15.64
65770-T9A-T00ZZ	CROSSMEMBER COMP,RR.FLOOR RR. bt / (S)	1	122.80	35	79.82	5.59	85.41
74940-TR0-003	BUZZER ASSYSMART cra / (S)	1	61.70	35	40.10	2.81	42.91
74450-T7M-H01	PROTECTORL.RR.WHEEL ARCH cra / (S)	1	172.10	35	111.86	7.83	119.69
39680-TV0-E01C5	SENSOR ASSYPARKING nw / (S)	1	89.70	35	58.30	4.08	62.38
39680-TV0-E11ZN	SENSOR ASSY PARKING T99 nw / (S)	1	67.80	35	44.07	3.08	47.15
39681-T7A-H01ZB	RETAINER PARKING SENSOR nec / (S)	2	67.80	35	88.14	6.17	94.31
	SUM PARTS:				2,374.99	166.26	2,541.25
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	340.00		340.00	23.80	363.80
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00

Supplementary

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0079037 / INDIA
Chassis No: MRHRU1830FP000834
License No: SLA8539M
Mileage: 74675
Engine No: L15Z71001525

Document No: SVO20035621
Printed By: IVANTEO
Order Date: 23. July 2020
Order Time: 11:55:30 AM
Service Advisor: IVAN TEO BOON KIAT

BOJSE	BODY JOINT SEALANT TAILGATE	1	120.00	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT END PANEL	1	120.00	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	120.00	120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00	140.00	9.80	149.80
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	325.00	325.00	22.75	347.75
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00	480.00	33.60	513.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00	480.00	33.60	513.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	650.00	650.00	45.50	695.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	350.00	350.00	24.50	374.50
BKRP02B	1729 CUT & RENEW RR FLOOR PANEL.END PANEL & DAMAGE PART RR CHASSIS INCLUDING FITTING ON ATTACHMENT ITEMS.	1	2,350.01	2,350.01	164.50	2,514.51
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,600.00	2,600.00	182.00	2,782.00
BOBC	BODY UNDERSIDE COATING (N)	1	300.00	300.00	21.00	321.00
			SUM LABOUR:	8,625.01	603.75	9,228.76
			TOTAL SGD	11,000.00	770.01	11,770.01

Total Payable (SGD)**11,770.01**

GST Amount is calculated from individual line(s)