Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20007467/KQF3E2

Date: 30/07/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001134217 Claimant Vehicle GBD8856A

Insured Vehicle No: SJT723Z No:

TP Date of Loss: 13/07/2020 Nature of Claim: Claim No: 245776

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD8856A

NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR Make & Model: Engine No:

K9KC400D054579 EURO 5 (M)

Reg. Date: 29/06/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0100192 Colour: White Odometer: 89212 km

Engine Capacity: 1461 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: Nο

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 175/70 R14 Rear Tyre Size: Front Left Side: Rear Left Side: Bridgestone 8 mm Bridgestone 8 mm Rear Right Side: Front Right Side: Bridgestone 8 mm Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,221.52	595.79	625.73	51.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	400.00	100.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,721.52	995.79	725.73	42.16
+ GST 7.00/7.00% (S\$)	120.51	69.71	50.80	42.15
Nett Amount (S\$)	1,842.03	1,065.50	776.53	42.16

INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 21/07/2020 Inspected At: Accord Auto Services Pte Ltd (HQ)

10 Ang Mo Kio Ind Park 2A #03-11, AMK

Auto Point

Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Part Source: (Last Synchronised: 30 Jul 2020)

Parts: N/A NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBD8856A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	563.10 FL	*563.10 FL
2	2		*FRONT BUMPER SIDE RETAINER	Serviceable	47.80 FL	*- FL
3	1		*FRONT REINFORCEMENT BAR	Repair	641.90 FL	*-FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	44.00 FS	*44.00 FS
5	1		*SET FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*45.00 FS
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.			
				Sub Total (S\$)	1,346.80	652.10
	- List Item Discount on L Items 10.00/10.00% (S\$)		125.28	56.31		
Total Parts (S\$)			1,221.52	595.79		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SPRAY PAINTING ON ALL AFFECTED AREA }	New	500.00	400.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA }	New	0.00	0.00
	Gross Labour Cost (S\$)		500.00	400.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >