

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG20007473/T1EA3Q2  
**Date:** 12/08/2021**REFERENCE**

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100410748-05 |
| <b>Claimant Vehicle No :</b> | SHB3111M                             | <b>Insured Vehicle No :</b> | SKS7475L      |
| Date of Loss:                | 20/07/2020                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 4265048156SG  |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHB3111M</b>                   |             |                   |
| Make & Model:               | HYUNDAI AE IONIQ HEV DCT, 1.6 (A) | Engine No:  | G4LEKU298670      |
| Reg. Date:                  | 24/07/2019 (Man. Year: 2019)      | Chassis No: | KMHC851CVKU164822 |
| Colour:                     | Yellow                            | Odometer:   | 79466 km          |
| Engine Capacity:            | 1580 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 195/65 R15   | Rear Tyre Size:  | 195/65 R15   |
| Front Left Side:  | Davanti 6 mm | Rear Left Side:  | Davanti 6 mm |
| Front Right Side: | Davanti 6 mm | Rear Right Side: | Davanti 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 2,706.12          | 1,592.76          | 1,113.36          | 41.14         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 970.00            | 580.00            | 390.00            | 40.21         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>3,676.12</b>   | <b>2,172.76</b>   | <b>1,503.36</b>   | <b>40.90</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>257.33</b>     | <b>152.09</b>     | <b>105.24</b>     | <b>40.90</b>  |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>3,933.45</b> | <b>2,324.85</b> | <b>1,608.60</b> | <b>40.90</b> |
|                                                 |                 | <hr/>           |                 |              |
| <b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b> |                 | 100.00          |                 |              |
| <b>+ Car Rental (2.0 x S\$62.60/day) (S\$)</b>  |                 | 125.20          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 7.49            |                 |              |
|                                                 |                 | <hr/>           |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>2,557.54</b> |                 |              |
|                                                 |                 | <hr/>           |                 |              |

INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 20/07/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars              | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRT RH DOOR LH MIRROR   | Not Necessary | 1,391.70 FL | *- FL        |
| 2   | 1   |          | *FRT RH DOOR LH ASSY     | Bent          | 1,797.20 FL | *1,797.20 FL |
| 3   | 1   |          | *FRONT DOOR CITYCAB LOGO | Necessary     | 75.00 FS    | *75.00 FS    |
| 4   | 1   |          | *REAR DOOR APP STICKER   | Necessary     | 80.00 FS    | *80.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>3,343.90</b> | <b>1,952.20</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 637.78          | 359.44          |
| <b>Total Parts (\$)</b>                                  | <b>2,706.12</b> | <b>1,592.76</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                       | Particulars                   | Lab.Type | Repairer's | Amount |
|--------------------------|-------------------------------|----------|------------|--------|
| <u>Labour Items</u>      |                               |          |            |        |
| 1                        | PANEL BEATING                 | New      | 450.00     | 320.00 |
| 2                        | SPRAY PAINTING                | New      | 400.00     | 200.00 |
| 3                        | TRANFER DOOR PART TO NEW DOOR | New      | 120.00     | 60.00  |
| Gross Labour Cost (\$\$) |                               |          | 970.00     | 580.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >