

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007474/KBA3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLZ671J	Insured Vehicle No :	SHC8393C
Date of Loss: 17/07/2020	Nature of Claim: TP	Claim No: MCT20070215

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ671J	Engine No:	R16B25500589
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650JT000533
Reg. Date:	23/04/2018 (Man. Year: 2018)	Odometer:	58562 km
Colour:	Metallic Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,991.80	1,452.72	3,539.08	70.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,050.00	1,570.00	59.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,611.80	2,502.72	5,109.08	67.12
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	7,611.80	2,000.00	5,611.80	73.73
+ GST 7.00/7.00% (\$\$)	532.83	140.00	392.83	73.73
Nett Amount (\$\$)	8,144.63	2,140.00	6,004.63	73.73
+ Car Rental (7.0 x S\$120.00/day) (\$\$)		840.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		3,009.00		
Global Sum Settlement (\$\$)		2,900.00		

INSPECTION

Date of Assignment:	20/07/2020	
Date Inspected:	20/07/2020 Inspected At:	Yee Auto Pte Ltd (HQ)
		160 SIN MING DRIVE, #02-17 SIN
		MING AUTOCITY
		Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ671J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Repair	950.50 F	*- FL
2	1		*FRONT DOOR GLASS OUTER MOULDING -LH	Serviceable	147.70 F	*- FL
3	1		*FRONT DOOR LOCK -LH	Repair	272.80 F	*- FL
4	1		*FRONT DOOR STICKER -LH	Not Necessary	56.50 F	*- FL
5	1		*FRONT DOOR SIDE MIRROR -LH	Serviceable	485.90 F	*- FL
6	1		*REAR DOOR -LH	Bent	985.10 F	*985.10 FL
7	1		*REAR DOOR GLASS OUTER MOULDING -LH	Serviceable	145.50 F	*- FL
8	1		*REAR DOOR HINGE -LH (LOWER)	Repair	90.50 F	*- FL
9	1		*REAR DOOR INNER TRIM BOARD -LH	Serviceable	585.10 F	*- FL
10	1		*REAR DOOR REGULATOR GEAR -LH	Distorted	197.90 F	*197.90 FL
11	1		*REAR DOOR REGULATOR GEAR MOTOR-LH	Jammed	303.10 F	*303.10 FL
12	1		*REAR DOOR STICKER	Necessary	56.50 F	*56.50 FL
13	1		*REAR DOOR WEATHERSTRIP -LH	Serviceable	129.50 F	*- FL
14	1		*REAR LOCKER PANEL COVER -LH	Mtg Cracked	585.20 F	*273.30 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,991.80	1,815.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	363.18
Total Parts (\$\$)	4,991.80	1,452.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,200.00	400.00
2	TO PUTTY ,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,200.00	600.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	120.00	30.00
4	TO CHECK WIRING FUNCTIONS	New	100.00	20.00
Gross Labour Cost (S\$)			2,620.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >