

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20007479/UBA3Q2

Date: 11/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJZ3108Z	Insured Vehicle No :	SHC8543L
Date of Loss: 13/07/2020	Nature of Claim: TP	Claim No: MCT20070158

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ3108Z		
Make & Model:	KIA CERATO FORTE, 1.6 EX (A)	Engine No:	G4FCAH362904
Reg. Date:	12/11/2010 (Man. Year: 2010)	Chassis No:	KNAFU411LA5200189
Colour:	Blue	Odometer:	82750 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,605.75	781.50	824.25	51.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,360.00	490.00	26.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	3,455.75	2,141.50	1,314.25	38.03
Approved Total (Overridden) (\$)		1,700.00		
(\$)	3,455.75	1,700.00	1,755.75	50.81
+ GST 7.00/7.00% (\$)	241.90	119.00	122.90	50.81
Nett Amount (\$)	3,697.65	1,819.00	1,878.65	50.81
+ Car Rental (5.0 x \$120.00/day) (\$)		600.00		
Nett Liability (\$)		2,419.00		
Global Sum Settlement (\$)		2,300.00		

INSPECTION

Date of Assignment:	05/10/2020	
Date Inspected:	05/10/2020 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok)
		Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
		Singapore 489977
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2020)
Parts:	143	KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ3108Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Badly Dented	700.00 FL	*315.00 FL
2	1		*FRONT DOOR RH	Badly Dented	700.00 FL	*700.00 FL
3	1		*FRONT DOOR TOP STICKER RH	Necessary	27.00 FL	*27.00 FL
4	1		*FRONT DOOR HINGE TOP RH	Not Necessary	28.00 FL	*- FL
5	1		*FRONT DOOR HINGE BOTTOM RH	Not Necessary	28.00 FL	*- FL
6	1		*REAR DOOR RH	Repair	632.00 FL	*- FL
7	1		*REAR DOOR TOP STICKER RH	Not Necessary	26.00 FL	*- FL
8	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
9	1		*ROCKER GARNISH RH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,141.00	1,042.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	535.25	260.50
Total Parts (\$\$)	1,605.75	781.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	800.00
3	ANTI-RUST COATING	New	150.00	60.00
Gross Labour Cost (S\$)			1,850.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >