

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20007483/R1VF3E2
Date: 28/07/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.	Policy No: DMCG20004205
Claimant Vehicle No : SKL1688R	Insured Vehicle No : GBJ4488Z
Date of Loss: 13/07/2020	Nature of Claim: TP Claim No: CDMCG20000953

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL1688R		
Make & Model:	LAMBORGHINI AVENTADOR LP700-4, 6.5 (A)	Engine No:	CEH004451
Reg. Date:	29/04/2011 (Man. Year: 2011)	Chassis No:	ZHWGE71J9BLA10702
Colour:	Green	Odometer:	0 km
Engine Capacity:	5204 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35Z R19	Rear Tyre Size:	235/35Z R19
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/07/2020	
Date Inspected:	21/07/2020	Inspected At: Eurosports Auto Pte Ltd (HQ) 24 Leng Kee Road #01-03 Singapore 159096
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value (Est) : \$285,000.00

OMV : \$254,648.00

PARF Rebate (1) : \$127,324.00

Quota Premium Paid : \$67,009.00

COE Rebate (2) : \$4,532.00

Total Rebate (1) + (2) = : \$131,856.00

The total amount incurred will be Market Value \$285,000.00 minus Total Rebate \$131,856.00 = \$153,144.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2020)
Parts:	M1-COUPE	LAMBORGHINI AVENTADOR LP700-4 6.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL1688R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >