



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

AIG Singapore

78 Shenton Way

Singapore 079120

Vehicle number	SMK6714Y
Make / Model	MERCEDES/C180
Chassis number	WDD2040312A801313
Accident date	17 July 2020
Reference	2007-21

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	1537.55 de ✓ 1350
2	FRONT BUMPER RETAINER	181.70 14x ✓ 248mm
1	FRONT BUMPER LOWER GRILLE	123.05 8mm
1	FRONT BUMPER SIDE GRILLE RH done ✓	77.05 2ut ✓
1	FRONT DAYLIGHT RH	559.00 ?cm ✓ 389.10
1	FRONT HEADLAMP RH	1406.45 mt ✓
1	FRONT HEADLAMP BRACKET RH	261.00 2x
1	FRONT FENDER INNER SHIELD	133.40 x
1	FRONT STEERING KNUCKLE RH	897.00 x } nx
1	FRONT LOWER ARM RH	606.05 x
1	FRONT KNUCKLE ARM BEARING RH	566.95 x
		6349.20 3222.60
Less 10 %		634.90
Subtotal		5714.30 2900.34
Balance C/F		
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	30.00 all ✓
1 SET	FRONT FENDER INNER SHIELD CLIP	20.00 xnn
1	RIM	1200.00 xnn
Subtotal		1250.00 30
Balance C/F		6964.30
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		6964.30
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	150.00 x nn
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 x nn
4	DIAGNOIS CHECK AND CLEAR FAULT CODE	400.00 200.
5	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREA	800.00 300
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 400.
7	APPLY ANTI RUST ON AFFECTED AREAS	80.00 x nn 930
7	REMOVE AND RENEW WRAPPING ON AFFECTED AREAS	700.00 x nn.
Subtotal		3190.00 3860.34
Grand total		9654.30 453100 # 3days #

Accepted by Reparer
Signature:
Date:

Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Link Auto Consultants hence notify the Reparer of the following:
• To resurvey before after spray painting

Tanji 97495749 - WP
21/7/2020 345

tanji & Muhammad. Inspgsm Resurvey after repair