

Vehicle number	SMK6714Y
Make / Model	MERCEDES/C180
Chassis number	WDD2040312A801313
Accident date	17 July 2020
Reference	2007-21

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER	1537.55 de ✓
2	FRONT BUMPER RETAINER	181.70 14x, RH?
1	FRONT BUMPER LOWER GRILLE	123.05 X
1	FRONT BUMPER SIDE GRILLE RH chose	77.05 2x ✓
1	FRONT DAYLIGHT RH	559.00 ?
1	FRONT HEADLAMP RH	1406.45 mt ✓
1	FRONT HEADLAMP BRACKET RH	261.00 ?
1	FRONT FENDER INNER SHIELD	133.40 X
1	FRONT STEERING KNUCKLE RH	897.00 X
1	FRONT LOWER ARM RH	606.05 X
1	FRONT KNUCKLE ARM BEARING RH	566.95 X
		6349.20
	Less 10 %	634.90
	Subtotal	5714.30
	Balance C/F	
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	FRONT BUMPER CLIP	30.00 all ✓
1 SET	FRONT FENDER INNER SHIELD CLIP	20.00 X
1	RIM	1200.00
	Subtotal	1250.00
	Balance C/F	6964.30
LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	6964.30
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	150.00 X
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 X
4	DIAGNOIS CHECK AND CLEAR FAULT CODE	400.00 200.
5	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREA	800.00 300
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 400.
7	APPLY ANTI RUST ON AFFECTED AREAS	80.00 X
7	REMOVE AND RNEW WRAPPING ON AFFECTED AREAS	700.00 X
	Subtotal	3190.00
	Grand total	9654.30

• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanji 97495749 - WP
21/7/2020 345

Tanji & Lukman. Lukman Resurvey after repair