



Section A - Accident Details

Registration Number	SHC4011G
Case Reference Number	TAX/07/20/2031
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHUA CHIN HOCK
Type of Accident	Side Swipe
Accident Date and Time	16/7/2020 3:00 PM
Accident Reported Date and Time	16/7/2020 3:52 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107564
Special Instruction to ARC, if any	TP / RIGHT REAR PORTION
Prepared Date and Time	17/7/2020 9:24 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$350.00
Total Spray Cost	\$2,412.00	\$750.00
Total Spare Part Cost	\$5,603.75	\$492.00
Total Other Cost	\$480.00	(\$242.00)
TOTAL COST	\$9,171.75	\$1,350.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	18/07/2020 10:03 AM	20/07/2020 10:43 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	
	L/S, after paint	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2007-0495	Invoice Number	
Quotation Date	30.07.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$676.00	\$350.00
Total Labour	\$676.00	\$350.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,412.00	\$750.00

/ Supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$352.00)
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	(\$242.00)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	0.00	\$423.90	0.00	\$0.00	Replace	Not Given X
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given X
		52462470 30	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
		52462470 20	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
		52462470 10	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given X
		52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given X
		52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given X
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685582
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/07/2020

User ID : PohSuan

		5256547900	FILLER, RR BUMPER , RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
		5256647900	FILLER, RR BUMPER , LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given X
		5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given X
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given X
		6700347210	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair R
		6875020122	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given X
		6877052031	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given X
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given X
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair R
		6563747060	LINER, REAR FENDER , RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given X
		4261147450	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair R
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given X
		7585047910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$576.00	25.00	\$432.00	Replace	Replace ✓
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
Total					\$7,323.84		\$492.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

492.00 /
+ 350.00 /
+ 860.00 /

1702.00 /

- 20%

1361.60 /

4 S \$ 1350 /
3 days