



Section A - Accident Details

Registration Number	SHF288K
Case Reference Number	TAX/07/20/2032
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SIM KAY TOH
Type of Accident	Side Swipe
Accident Date and Time	16/7/2020 5:30 PM
Accident Reported Date and Time	17/7/2020 9:09 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107567
Special Instruction to ARC, if any	TP / RIGHT FRONT PORTION
Prepared Date and Time	17/7/2020 10:37 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$4,428.31	\$2,798.34
Total Other Cost	\$340.00	\$20.00
TOTAL COST	\$6,002.31	\$3,218.34 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	17/07/2020 10:51 AM	17/07/2020 2:27 PM
Signature		
Remarks		P/P, before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2007-0395	Invoice Number	
Quotation Date	28.07.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$340.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given
		53112-47310	GRILLE, RADIATOR	0.00	\$178.60	0.00	\$0.00	Replace	Not Given
		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		52611-47210	ABSORBER, FR BUMPER	0.00	\$80.20	0.00	\$0.00	Replace	Check
		52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$716.60	0.00	\$0.00	Replace	Not Given
		52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$132.70	0.00	\$0.00	Replace	Not Given
		52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given
		52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$246.10	0.00	\$0.00	Replace	Not Given
		51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Not Given
		53213-47050	SUPPORT, RADIATOR UPPER RH	0.00	\$78.90	0.00	\$0.00	Replace	Not Given
		81145-47890	UNIT, HEADLAMP, RH	1.00	\$2,637.60	10.00	\$2,373.84	Replace	Replace
		53875-47120	LINER, FR FENDER, RH	0.00	\$202.50	0.00	\$0.00	Replace	Not Given
Total					\$5,336.40		\$2,798.34		

2798.34
+ 200.00
+ 220.00
3218.34

Added Spare Parts / Material Usage After Surveyor Signed off



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/07/2020

User ID : PohSuan

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									