Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20007492/T1TF3E2

**Date:** 29/07/2020

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: ML000131

Claimant Vehicle SHA9521D Insured Vehicle No: SLF9570M

No:

Date of Loss: 18/07/2020 Nature of Claim: TP Claim No: M2003525

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHA9521D

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR946010

Reg. Date: 21/10/2016 (Man. Year: 2016) Chassis No: JTDKB3FU503534284

Colour: Yellow Odometer: 527390 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Davanti 6 mm Rear Left Side: Davanti 6 mm
Front Right Side: Davanti 6 mm Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,802.97	2,264.97	1,538.00	40.44
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,870.00	1,570.00	300.00	16.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,683.97	3,845.97	1,838.00	32.34
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	5,683.97	3,050.00	2,633.97	46.34
+ GST 7.00/7.00% (S\$)	397.88	213.50	184.38	46.34
Nett Amount (S\$)	6,081.85	3,263.50	2,818.35	46.34

**INSPECTION** 

Date of Assignment: 20/07/2020 Present Location: ComfortDelGro Engineering Pte Ltd

(Loyang)

Date Inspected: 20/07/2020 Inspected At: ComfortDelGro Engineering Pte Ltd

(Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## **REPAIR DETAILS**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2020)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA9521D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR FENDER RH	Repair	836.70 FL	-	*- FL
2	1		*REAR DOOR RH	Bent	1,258.30 FL	-	*1,258.30 FL
3	1		*REAR ROCKER RH	Repair	576.00 FL	-	*- FL
4	1		*REAR BUMPER	Repair	458.60 FL	-	*- FL
5	1		*REAR BUMPER BRACKET RH	Not Necessary	112.70 FL	-	*- FL
6	1		*REAR RIM RH	Cut	1,555.00 FL	-	*1,555.00 FL
7	1		*FRT DOOR CCPL LOGO	Necessary	75.00 FS	-	*75.00 FS
8	1		*REAR DOOR CCPL APP LOGO	Necessary	80.00 FS	-	*80.00 FS
9	1		*BUMPER MAT	Not Necessary	50.00 FS	-	*-FS
F=Fra	anchise	part. S=SpcI	Nett. L=ListItemDisc.	'			
				Sub Total (S\$)	5,002.30	2,968.30	
			- List Item Discount on L Items	s 25.00/25.00% (S\$)	1,199.33	703.33	
				Total Parts (S\$)	3,802.97		2,264.97
				'			

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	OD/TP Case (Insurer)	_	11.00	11.00
			Sub Total (S\$)	11.00	11.00

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATIING	New	760.00	640.00
2	SPRAY PAINTING	New	800.00	800.00
3	REMOVE/REFIX DOOR PARTS	New	120.00	60.00
4	TOFF KOTE	New	100.00	40.00
5	CHECK WIRING	New	90.00	30.00
		Gross Labour Cost (S\$)	1,870.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >