



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20200719/0648		LOCATION OF FIRE: Junction of Jalan Boon Lay and Boon Lay Way	
FIRE REPORTED ON : 19 July 2020			
TIME OF CALL : 18:53:22 hrs			
STATION COVERAGE : Jurong Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine compartment of a BMW car (SJA3323A).			
METHOD OF EXTINGUISHMENT: By SCDF using a hose reel jet from a fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine compartment of the car was damaged. The front part of the car, including but not limited to the windscreen, dashboard and interior of the car, sustained heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
 HUANG WEI KANG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.