

Naz

AXA

ASSIGNMENT

From _____ Date 21/07/2020

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

at Workshop m/s AK LIM MOTOR
of AMK AUTOPOINT

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



☒ Bal or Market Value:

32 K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SSA 3323 A Yr Regn: 30 JUL 2010

Type ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: BMW 535i

c.c 2,979

Colour WHITE

A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading N/A

T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No:

C/No: UBAFR720406579971

Gen. Cond: Good / Fair / Poor / ☒ Burnt

Steering: Inorder / Jammed / Leaked / ☒ Burnt or

Brake: Inorder / Jammed / Leaked / ☒ Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 255/35 R20

R: 11

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 6 mm

L/Bal. 5 mm

L/Bal. 6 mm

D.O.A. 19/7/2020

D.O.I. 21/7/2020

Survey held at AK LIM MOTOR

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

AXA CLS

Date / Time	Action / Instruction
	<u>uneconomical to repair. Recommend total loss.</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Form No: _____

Form Code / REF: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Wash & Dry (\$)

Survey Fee:

Transportation:

1) 3 + PS \$1

2) Flights

3) Other

700 1