

Section A - Accident Details

Registration Number	SHB1679E
Case Reference Number	TAX/07/20/2033
Registration Date	10/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOY KIM HOONG (MEI JIANXIONG)
Type of Accident	Head To Side
Accident Date and Time	17/7/2020 6:55 AM
Accident Reported Date and Time	17/7/2020 9:56 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107568
Special Instruction to ARC, if any	TP / LEFT FRONT PORTION
Prepared Date and Time	17/7/2020 12:41 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$350.00
Total Spray Cost	\$1,476.00	\$400.00
Total Spare Part Cost	\$7,010.52	\$1,527.91
Total Other Cost	\$700.00	\$50.00
TOTAL COST	\$9,862.52	\$2,327.91
Lump Sum Total	\$9,850.00	\$2,350.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / EQ
ARC / Surveyor Sign Off Date	20/07/2020 10:54 AM	20/07/2020 10:44 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	L/S, after paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2008-0001	Invoice Number	
Quotation Date	03.08.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	\$676.00	\$350.00
Total Labour	\$676.00	\$350.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$700.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check
		52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check

CRU

NEC

SVC

BR

SVC

81521-47050	LENS & BODY,FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace ✓	CRU
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given X	SVC
53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given X	SVC
76851-47020	BUMPER LIP FRT	1.00	\$139.60	100.00	\$0.00	Replace	Repair ✓	R
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check X	SVC
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given X	SVC
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace ✓	CRA
53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair ✓	R
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓	NEC
53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X	SVC
53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given X	SVC
53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given X	SVC
53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given X	SVC
42611-47140	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given X	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X	SVC
43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given X	SVC
87940-47310	MIRROR ASSY,LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given X	SVC
81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X	SVC
87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given X	SVC
Total			\$11,095.25		\$1,781.11			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		53876-47030	FENDER LINER FRT/LH (supp)	1.00	\$171.70	25.00	\$128.78	Replace	Replace ✓
Total					171.70		128.78		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

3 days

1909.89 /

- 207

1527.91 /

+ 350.00 /

+ 450.00 /

2327.91 /

45 \$2350 / -